

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG20011733/KPA3Q2-1**Date:** 26/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900008648
<b>Claimant Vehicle No :</b>	PC3457R	<b>Insured Vehicle No :</b>	SMH4348A
Date of Loss:	27/10/2020	Nature of Claim:	TP
		Claim No:	8101385796SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>PC3457R</b>		
Make & Model:	TOYOTA HIACE, 3.0 D DX DIESEL TURBO MT 2WD	Engine No:	1KD2424436
	LGV (M)		
Reg. Date:	14/03/2015 (Man. Year: 2014)	Chassis No:	KDH2010145702
Colour:	Silver	Odometer:	290633 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Goodride 7 mm	Rear Left Side:	Goodride 7 mm
Front Right Side:	Goodride 7 mm	Rear Right Side:	Goodride 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	577.72	577.72	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	890.00	700.00	190.00	21.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,467.72</b>	<b>1,277.72</b>	<b>190.00</b>	<b>12.95</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,000.00</b>		
<b>(S\$)</b>	1,467.72	1,000.00	467.72	31.87
<b>+ GST 7.00/7.00% (S\$)</b>	102.74	70.00	32.74	31.87
<b>Nett Amount (S\$)</b>	<b>1,570.46</b>	<b>1,070.00</b>	<b>500.46</b>	<b>31.87</b>
<b>+ Loss of Use (3.0 x S\$90.00/day) (S\$)</b>		270.00		
<b>+ Doc/Search Fee (S\$)</b>		8.00		
<b>Nett Liability (S\$)</b>		<b>1,348.00</b>		

INSPECTION

Date of Assignment:	28/10/2020	
Date Inspected:	09/11/2020	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	3.0 days	

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Distorted	495.10 FL	*495.10 FL
2	1		*REAR BUMPER LH SIDE RETAINER	Distorted	40.40 FL	*40.40 FL
3	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
4	1		*LH TAILLAMP	Cracked	213.80 FL	*213.80 FL
F=Franchise part. L=ListItemDisc.						
					Sub Total (S\$)	770.30 770.30
					- List Item Discount on L Items 25.00/25.00% (S\$)	192.58 192.58
					Total Parts (S\$)	577.72 577.72

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIX REAR BUMPER ASSY ,TAILLAMP ,KNOCK & REPAIR REAR LH SIDE PANEL & REALIGN THE SAME	New	450.00	400.00
2	PUTTY & RESPRAY ON REAR LH SIDE PANEL	New	400.00	260.00
3	REMOVE & REFIX REVERSE SENSOR & CHECK SYSTEM	New	40.00	40.00
<b>Gross Labour Cost (\$)</b>			<b>890.00</b>	<b>700.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >