

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22003968/ANCE2

Date: 20/09/2022

REFERENCE

Insured/Claimant: NG PUI YEE (WU PEIYI) Policy No: 7210000336
Date of Loss: 21/04/2022 Nature of Claim: OD Claim No: 9444025490SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMX4622Z**
Make & Model: AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A) Engine No: CZDC22958
Reg. Date: 13/01/2021 (Man. Year: 2020) Chassis No: WAUZZZF38M1059491
Colour: White Odometer: 23953 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$170,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,462.00	9,659.68	9,802.32	50.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,472.00	1,972.00	9,500.00	82.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,934.00	11,631.68	19,302.32	62.40
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	30,534.00	11,231.68	19,302.32	63.22
+ GST 7.00/7.00% (S\$)	2,137.38	786.22	1,351.16	63.22
Nett Amount (S\$)	32,671.38	12,017.90	20,653.48	63.22

INSPECTION

Date of Assignment: 28/04/2022
Date Inspected: 27/04/2022 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	1,235.00 FS	*987.60 FS
2	1	*FRONT BUMPER CLOSING ELEMENT - RH	Deformed	66.00 FS	*52.32 FS
3	1	*FRONT BUMPER GRILLE - CENTER	Deformed	242.00 FS	*193.60 FS
4	1	*FRONT BUMPER GRILLE - RH	Missing	124.00 FS	*98.80 FS
5	1	*FRONT BUMPER CLOSING ELEMENT	Not Necessary	212.00 FS	*- FS
6	1	*FRONT BUMPER SPOILER	Deformed	426.00 FS	*340.80 FS
7	1	*FRONT BUMPER AIR GUIDE GRILLE - RH	Missing	171.00 FS	*136.40 FS
8	1	*RADIATOR GRILLE	Cracked	1,594.00 FS	*1,275.20 FS
9	1	*RADIATOR GRILLE STRIKER PLATE	Cracked	271.00 FS	*216.80 FS
10	1	*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	114.00 FS	*- FS
11	1	*FRONT BUMPER REINFORCEMENT BEAM	Broken	974.00 FS	*778.80 FS
12	1	*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	43.00 FS	*- FS
13	1	*FRONT FENDER - RH	Not Necessary	1,445.00 FS	*- FS
14	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	66.00 FS	*- FS
15	1	*FRONT FENDER BRACE - RH	Not Necessary	98.00 FS	*- FS
16	1	*FRONT WHEEL HOUSING LINER - RH	Not Necessary	260.00 FS	*- FS
17	1	*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	105.00 FS	*- FS
18	2	*FRONT WHEEL ARCH COVER - LH / RH	Necessary	566.00 FS	*452.00 FS
19	1	*HEADLIGHT - LH	Cut	5,952.00 FS	*4,761.60 FS
20	1	*HEADLIGHT POWER MODULE	Not Necessary	850.00 FS	*- FS
21	1	*LED HEAT SINK	Not Necessary	870.00 FS	*- FS
22	1	*HEADLIGHT MOUNTING - RH	Cracked	132.00 FS	*105.20 FS
23	1	*LIFT CYLINDER - RH	Not Necessary	231.00 FS	*- FS
24	2	*FRONT PARKING AID SENSOR	Not Necessary	530.00 FS	*- FS
25	1	*HORN - RH	Not Necessary	145.00 FS	*- FS
26	1	*HORN SUPPORT - RH	Not Necessary	25.00 FS	*- FS
27	1	*LOCK CARRIER	Not Necessary	1,412.00 FS	*- FS
28	1	*RADIATOR AIR GUIDE - RH	Cracked	43.00 FS	*34.08 FS
29	4	*RADIATOR COOLANT	Not Necessary	188.00 FS	*- FS
30	1	*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
31	1	*SUNDRIES	Not Necessary	400.00 FS	*- FS
32	1	*FRONT BUMPER TOP COVER Supplementary	Cracked	137.00 FS	*109.60 FS
33	1	*STICKER FOR AIR CONDITIONER Supplementary	Necessary	9.00 FS	*6.64 FS
34	1	*SIGN CAUTION STICKER Supplementary	Necessary	16.00 FS	*12.40 FS
35	1	*RADIATOR AIR GUIDE - LOWER Supplementary	Cracked	48.00 FS	*37.84 FS
36	1	*REFRIGERANT LINE (A/C COMPRESSOR -> A/C CONDENSER) Supplementary	Not Necessary	402.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 19,462.00 9,659.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY, FRONT PARKING AID AND FRONT CAMERA ASSY	New	480.00	480.00
2	TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,200.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,800.00	500.00
4	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET	New	2,700.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	250.00
7	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, CHARGED AIR COOLER, ELECTRICAL FANS AND CONTROL UNIT. TO PRESSURISE COOLING SYSTEM	New	1,700.00	0.00
			Gross Labour Cost (\$)	11,472.00
				1,972.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >