Adjuster Report 3/13/23, 9:43 AM

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI22003971/KVY3E2

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

13/03/2023 Date: Singapore 079909

REFERENCE

Insured/Claimant: AMY SPA & FOOT REFLEX DMPCSNW00079522100 Policy No:

Date of Loss: 14/04/2022 Nature of Claim: Claim No: SNM22D202666/C01/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA2910M**

TOYOTA WISH, 1.8 (A) Make & Model: Engine No: 2ZR1720247

26/02/2016 (Man. Year: 2016) Chassis No: JTDGG20W50J003688 Reg. Date:

Colour: Metallic Pearl White Odometer: 84045 km

1798 cc **Engine Capacity:** Market Value/New Car Price: S\$61,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Footbrake (Serviceable): Steering (Serviceable): Yes Yes

Engine Modification: Pre-accident Condition: Handbrake (Serviceable): Yes No

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm Front Right Side: Rear Right Side: Yokohama 7 mm Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,325.00	1,835.00	490.00	21.08
Miscellaneous Items		195.00	195.00	0.00	0.00
Labour		1,688.29	1,495.09	193.20	11.44
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	4,208.29	3,525.09	683.20	16.23
	Approved Total (Overridden) (S\$)		3,150.00		
	(S\$)	4,208.29	3,150.00	1,058.29	25.15
	+ GST 7.00/8.00% (S\$)	294.58 252.00 42.58	14.45		
	Nett Amount (S\$)	4,502.87	3,402.00	1,100.87	24.45

INSPECTION

Date of Assignment: 28/04/2022 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun Industrial Park A Date Inspected: 28/04/2022 Inspected At:

Singapore 768761

Estimated Period of Repair: 7.0 days

KENNETH KONG VERON CHEN Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Mar 2023)

Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for SLA2910M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1 F=Franchise part.	*PARTS		2,325.00 F	*1,835.00 F
i –i talicilise part.		Total Parts (S\$)	2,325.00	1,835.00
	Repo	rt was unsubmitted during this print-out.		

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Mis	cella	neous Items		
1	1	EXTRAS	95.00	95.00
2	1	SUNDRY (NECESSARY)	100.00	100.00
			Sub Total (S\$) 195.00	195.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR	New	861.00	667.80
2	SPRAY PAINTING	New	827.29	827.29
		Gross Labour Cost (S\$)	1,688.29	1,495.09
		Report was unsubmitted during this print-out.		

< END OF ESTIMATES >