

Cheng Hoe Motor Pte Ltd
#01-374/382, Blk 1019, Yishun
Industrial Park A
768761

Insurer Reference: SLA2910M
Repairer Reference: A0407
Date calculated: 25/04/2022 11:24 AM

Full Report
Registration: SLA2910M
Printed: 25/04/2022 11:24 AM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	CHENG HOE	Currency:	SGD
Claim Reference:	SLA2910M	Date of Incident:	14/04/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	TOYOTA		
Model:	WISH(ZGE21L/ZGE2)		
Sub Model:	BASE MODEL		
Model Sheet Number:	70 W2 01		
Registration:	SLA2910M		
VIN number:	JTDGG20W50J003688		
Odometer:			
Model Specs			
AIR CONDITIONING	FOG LAMPS	1.8 LTR 95 KW	PROD JAPAN
TWO COAT METALLIC	PREPARE OFF VEHICLE		

Not Authorized
1/1/2022
Henry Ate Pany

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Code	Description	WU	Price SGD
	COMBINATION SWITCH, INSTRUMENTS, CENTRE CONSOLE AND NECESSARY ATTACHED PARTS AND TRIMS		
550451)	RENEW INSTRUMENT PANEL (REMOVED)	6.0	25.20
0340	FRONT BUMPER SUPPORT REPAIR	6.0	42.00
0742	R/F WING REPAIR	10.0	63.00
1009	FRONT PANEL CPL REPAIR	6.0	42.00
2351	ROOF REPAIR	6.0	336.00
Labour Cost			
	Panel / Mechanical Labour	Hrs 20.50 WU 205.0	861.00
	Total of Labour		861.00

Paint

Code	Description - TWO COAT METALLIC	WU	Price SGD
	BONNET NEW PART PAINTING	15.0	
	L/F WING REPAIR PAINTING >50%	17.0	
	R/F WING REPAIR PAINTING >50%	17.0	
	ROOF REPAIR PAINTING >50%	62.0	
	FRONT PANEL CPL SURFACE PAINT	6.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	42.83
0741	L/F WING REPAIR PAINTING >50%	16.59
0742	R/F WING REPAIR PAINTING >50%	16.59
2351	ROOF REPAIR PAINTING >50%	112.58
1009	FRONT PANEL CPL SURFACE PAINT	13.70

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			117.0	
Preparation Main Work Metal		2.50	25.0	105.00
Total	10 WU/h	14.20	142.0	596.40

Material Cost - Paint

	Price SGD
New Part Painting	42.83
Repair Painting	145.76
Surface-/Blend Paint	13.70
Material-constant Metal Preparation	28.60
Total	230.89

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01
				Price SGD

Code	Description	Part Number	Part Source	Price SGD
0471	BONNET	53301 68020	Original	350.00 ✓
1416	CHECK	56116 22050		0.00
1415	CLIP FASTENING	56115 30100		0.00
0281	FRONT BUMPER	52119 68130A0	Original	250.00 ✓
1413	FRT SCREEN MNTG KIT	USE SINGLE PARTS		
2427	L/F DRIP RAIL MLDG	75552 68020	Original	100.00 ✓
0431	MANUFACTURER BADGE	75303 68010	Original	30.00 ✓
0318	R/F BUMPER BRACKET	52115 68040	Original	35.00 ✓
2428	R/F DRIP RAIL MLDG	75551 68020	Original	100.00 ✓
0562	RIGHT HEADLAMP ASSY	81130 68070	Original	420.00 ✓
1408	UPP FRT SCREEN SEAL	56118 68020		0.00
4331	UPP INSTRUMENT PANEL	55302 68900B0	Original	490.00 ?
1401	WINDSCREEN	56101 68060	Original	500.00 ✓
1411	WINDSCREEN REP KIT	KNGKW12		0.00
1412	WINDSCREEN SEAL	56117 68020	Original	50.00 ✓
Savings				0.00
Subtotal				2,325.00
Fixed Sundry Parts Price				100.00
Total				2,425.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Extras

Code	Description	Price SGD
1000	WINDSCREEN SEALANT	40.00* ✓
1001	FRT NO. PLATE	35.00* ✓
1002	ERP BRACKET	20.00* ✓
Total Extras		95.00

Final Calculation

	SGD	SGD
Parts		
Fixed Sundry Parts Price	2,325.00	
Total Parts	100.00	2,425.00
Labour Time Base 10 WU/h		
Total 205.0 WU X 42.00 SGD/h	861.00	
Total of Labour		861.00
Total Of Extras		95.00
Paint Work Time Base 10 WU/h		
Labour Cost 142.0 WU X 42.00 SGD/h	596.40	
Material Cost	230.89	
Total Paint Including Material		827.29
Repair Cost Excludes GST		4,208.29
GST (+7.0%)		294.58
Repair Cost Included GST		4,502.87

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☒
Underbody ☐



Tyres Condition

Tyre Brand	Tread (Left Middle), mm	Tread (Left Outer), mm	Tread (Left Inner), mm	Tread (Right Inner), mm	Tread (Right Outer), mm	Tread (Right Middle), mm	Condition
------------	-------------------------	------------------------	------------------------	-------------------------	-------------------------	--------------------------	-----------

Spare Tyre Brand	Tread (Spare), mm
------------------	-------------------

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
810151A	ADJUST HEADLAMP		3.0	12.60
520011)	R + R FRONT BUMPER		3.0	12.60
520011)	RENEW FRONT BUMPER (REMOVED)		6.0	25.20
	INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT			
810051)	R + R RIGHT HEADLAMP		7.0	29.40
530051)	TRANSFER ATTACHED PARTS FROM BONNET		3.0	12.60
530051)	RENEW BONNET		1.0	4.20
	INCLUDES: R + R OR RENEW ATTACHED PARTS			
530111	R + R BONNET LOCK		2.0	8.40
554011	R + R FRONT SCREEN		30.0	126.00
	INCLUDES: TRIM, WIPER ARMS, DRIP RAIL MOULDING, A-PILLAR TRIM, EDGE PROTECTION, SUN VISORS AND INTERIOR MIRROR			
743201	R + R HEADLINING		22.0	92.40
550451)	R + R INSTRUMENT PANEL		7.0	29.40
	INCLUDES: R + R STEERING WHEEL, AIRBAG,			