

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003974/VNY3Q2**Date:** 02/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00083112200

Claimant Vehicle No : SKG8077J **Insured Vehicle No :** SNE5762J

Date of Loss: 22/04/2022 Nature of Claim: TP Claim No: SNM22D202809/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKG8077J**

Make & Model: MERCEDES-BENZ SLK 200 COUPE, 2.0 (A) Engine No: 27195431090726

Reg. Date: 24/10/2008 (Man. Year: 2008) Chassis No: WDB1714452F202480

Colour: Black Odometer: 141283 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18

Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,907.99	2,019.52	1,888.47	48.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	800.00	700.00	46.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,407.99	2,819.52	2,588.47	47.86
Approved Total (Overridden) (S\$)		2,250.00		
(S\$)	5,407.99	2,250.00	3,157.99	58.39
+ GST 7.00/7.00% (S\$)	378.56	157.50	221.06	58.39
Nett Amount (S\$)	5,786.55	2,407.50	3,379.05	58.39

INSPECTION

Date of Assignment: 28/04/2022

Date Inspected: 29/04/2022 Inspected At: Success United Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 Aug 2022)

Parts: M1-COUPE MERCEDES-BENZ SLK 200 COUPE 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKG8077J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Repair	2,098.30 FL	*- FL
2	1		*REAR BUMPER SIDE HOLDER LH	Necessary	152.80 FL	*152.80 FL
3	1		*REAR SPORTS RIM LH	Scratched	980.00 FL	*980.00 FL
4	1		*3 MATT STICKER FOR REAR FENDER & REAR BUMPER	Necessary	1,000.00 FS	*1,000.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,231.10	2,132.80
- List Item Discount on L Items 10.00/10.00% (\$)	323.11	113.28
Total Parts (\$)	3,907.99	2,019.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODY PARTS, REALIGN BODYWORKS AND WHERE CONSISTENT TO TGE ACCIDENT	New	800.00	400.00
2	TO PUTTY AND RESPRAY PAINTING ON THE AFFECTED AREA	New	700.00	400.00
Gross Labour Cost (\$\$)			1,500.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >