



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNC 4168S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER SPORT ASSY	DISTORTED	1,178.00	1,150.00
1	REAR BUMPER LEFT BRACKET	NO SUCH PARTS	64.00	-
1	REAR BUMPER LEFT RETAINER	BENT	67.00	35.00
1	REAR BUMPER LEFT REFLECTOR WITH GARNISH	CRACKED	206.00	206.00
1	REAR BUMPER REINFORCEMENT	BENT	387.00	188.00
1	REAR BOOTLID OUTER LOCK SENSOR	NOT NECESSARY	252.00	-
1	REAR BOOTLID INNER LOCK SWITCH ASSY	NOT NECESSARY	365.00	-
1	REAR BOOTLID ASSY	NOT NECESSARY	1,286.00	-
1	REAR BOOTLID CENTRE LOGO	NOT NECESSARY	68.00	-
1	REAR BOOTLID "CIVIC" EMBLEM	NOT NECESSARY	56.00	-
1	REAR BOOTLID "I-VTEC" EMBLEM	NOT NECESSARY	56.00	-
1	REAR BOOTLID OUTER GARNISH	NOT NECESSARY	355.00	-
1	REAR BOOTLID INNER TRIM BOARD	NOT NECESSARY	295.00	-
4	REAR BOOTLID RUBBER STOPPER	NOT NECESSARY	60.00	-
1	REAR BOOTLID WEATHERSTRIP	NOT NECESSARY	188.00	-
1	REAR BOOTLID LOCK MECHANISM	NOT NECESSARY	225.00	-
1	REAR BOOTLID LOCK CATCH	NOT NECESSARY	68.00	-
1	REAR LEFT BOOTLID TAILLAMP	NOT NECESSARY	434.00	-
1	REAR LEFT TAILLAMP	CRACKED	688.00	321.10
1	REAR LEFT TAILLAMP LOWER BRACKET	CRACKED	118.00	45.50
1	REAR NO PLATE LAMP	NOT NECESSARY	98.00	-
1	REAR END PANEL	DENTED	955.00	277.50
1	REAR END LOWER PANEL TOP GARNISH	NOT NECESSARY	128.00	-
	LESS 20% DISCOUNT		-1,519.40	-444.62
			6,077.60	1,778.48
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	40.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	1,200.00	200.00
1	REAR NO PLATE WITH GARNISH (SN)	NOT NECESSARY	100.00	-
1	SET REAR BOOTLID OUTER GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-

Report Ref No. CS/AGI22003975/Uvy3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
8	REAR BOOTLID INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR END PANEL SEALANT (SN)	NECESSARY	140.00	50.00
6	REAR END LOWER PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR VIEW CAMERA (SN)	NOT NECESSARY	450.00	-
1	REAR BUMPER LEFT LOWER SPOILER GRILLE (SN)	DISTORTED	280.00	180.00
1	REAR BUMPER LEFT LOWER SPOILER OUTER COVER (BLUE)(SN)	NO SUCH PARTS	250.00	-
1	REAR BOOTLID TOP SPOILER COMPLETE ASSY (SN)	NOT NECESSARY	1,400.00	-
1	REAR BOOTLID TOP SPOILER SEALANT (SN)	NOT NECESSARY	100.00	-
1	REAR BUMPER LEFT SPOILER (SN)	NO SUCH PARTS	450.00	-
1	SET REAR BUMPER SPOILER CLIPS (SN)	NECESSARY	40.00	30.00
1	REAR BUMPER LEFT SPOILER SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR BUMPER LOWER SPOILER (SN)	BROKEN	1,600.00	900.00
12	REAR BUMPER LOWER SPOILER CLIPS (SN)	REPEATED	50.00	-
1	REAR BUMPER LOWER SPOILER SEALANT (SN)	REPEATED	100.00	-
			6,450.00	1,400.00
	<b>LABOUR</b>			
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN REAR LEFT AFFECTED AREA AND REPLACE REAR LEFT DAMAGED PARTS.		1,400.00	880.00
	TO PUTTY AND SPRAY PAINTING REAR AND REAR LEFT PORTION.		1,400.00	900.00
	TO CHECK REAR LIGHTING AND WIRING.		50.00	20.00
	TO REMOVE AND INSTALL REAR BOOTLID LOCK MECHANISM.	NOT NECESSARY	80.00	-
	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.		140.00	80.00
	TO REPAIR ALIGN AND STRAIGHTEN REAR LEFT FENDER PANEL ASSY	NOT NECESSARY	300.00	-
	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA.		140.00	40.00
	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR.		80.00	50.00
	TO REMOVE AND INSTALL REAR VIEW CAMERA.	NOT NECESSARY	80.00	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING SERVICE.	NOT NECESSARY	100.00	-
			3,770.00	1,970.00
GRAND TOTAL			16,297.60	5,148.48
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,100.00

Report Ref No. CS/AGI22003975/Uvy3n2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.