

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/HLA22003986/AQY3E2

Date: 29/06/2022

REFERENCE

Handling Insurer: HL Assurance Pte Ltd Policy No: MP317463
Claimant Vehicle No : YQ6197R Insured Vehicle No : SGX8138A
Date of Loss: 26/04/2022 Nature of Claim: TP Claim No: MPC03364/LJ

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YQ6197R
Make & Model: TOYOTA DYNA 150, 2.8 D 6 (A) Engine No: 1GD8871364
Reg. Date: 18/03/2022 (Man. Year: 2021) Chassis No: JHHAGV4680K001703
Colour: Silver Odometer: 5323 km
Engine Capacity: 2755 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/75 R15 Rear Tyre Size: 145/80 R13
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,370.10	3,384.72	985.38	22.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	1,960.00	1,220.00	38.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,550.10	5,344.72	2,205.38	29.21
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	7,550.10	4,200.00	3,350.10	44.37
+ GST 7.00/7.00% (S\$)	528.51	294.00	234.51	44.37
Nett Amount (S\$)	8,078.61	4,494.00	3,584.61	44.37

INSPECTION

Date of Assignment: 28/04/2022
Date Inspected: 28/04/2022 Inspected At: SM Automotive (HQ)
Blk C, 1 Kaki Bukit Avenue 6 #01-43
Singapore 417883
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Jun 2022)	
Parts:	N/A	TOYOTA DYNA 150 2.8 D 6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ6197R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,314.90 FL	*1,314.90 FL
2	1		*REAR TAILGATE LOCK RH	Dented	230.70 FL	*230.70 FL
3	1		*REAR TAILGATE EMBLEM STICKER TOYOTA	Necessary	301.20 FL	*301.20 FL
4	1		*REAR TAILGATE EMBLEM STICKER DYNA	Necessary	61.90 FL	*61.90 FL
5	1		*REAR TAILLAMP RH	Cracked	378.90 FL	*378.90 FL
6	1		*REAR TAILLAMP BRACKET RH	Bent	270.10 FL	*270.10 FL
7	1		*REAR TAILGATE RUBBER STOPPER RH	Cut	61.30 FL	*61.30 FL
8	1		*REAR REFLECTOR ROUND	Cracked	28.90 FL	*28.90 FL
9	1		*REAR EXHAUST MUFFLER	Not Necessary	980.50 FL	*- FL
10	1		*REAR NUMBER PLATE BRACKET	Bent	158.40 FL	*158.40 FL
11	1		*REAR SAFETY BAR	Dented	850.00 FS	*800.00 FS
12	2		*REAR SAFETY BAR BRACKET	Bent	280.00 FS	*200.00 FS
13	1		*REAR SAFETY BAR STICKER	Necessary	120.00 FS	*80.00 FS
14	1		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,316.80	4,086.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	946.70	701.58
Total Parts (\$\$)	4,370.10	3,384.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,200.00	700.00
2	LABOUR FOR SPRAYPAINTING	New	800.00	700.00
3	WIRING CHECK	New	80.00	30.00
4	TO APPLY TUFF COATING / RUST PROOF ACCIDENT AREAS	New	300.00	80.00
5	LABOUR FOR REPAIR & STRAIGHTEN BOTH REAR CHASSIS FRAME	New	500.00	200.00
6	LABOUR FOR REMOVE & RENEW REAR EXHAUST MUFFLER, TO REPAIR & STRAIGHTEN REAR EXHAUST PIPE	New	300.00	250.00
Gross Labour Cost (\$\$)			3,180.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >