



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 1518J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEADLAMP LH	CRACKED	1,835.00	1,835.00
1	FRONT BUMPER	DEFORMED	400.00	400.00
1	FRONT BUMPER RETAINER	DAMAGED	68.00	68.00
1	FRONT BUMPER PROTECTOR	DEFORMED	106.00	106.00
1	FRONT FENDER LH	DENTED	845.00	845.00
1	FRONT FENDER COWLING LH	TORN	108.00	108.00
	LESS 25% DISCOUNT		-840.50	-840.50
			2,521.50	2,521.50
	<u>SPECIAL NETT ITEMS</u>			
1	FENDER COWLING CLIP (SN)	NECESSARY	50.00	30.00
1	FRONT BUMPER TRD FRONT LIP (SN)	TO REPAIR SEE LABOUR	880.00	-
1	FRONT FENDER TRD FENDER ARCH (SN)	DEFORMED	780.00	480.00
1	SPORT RIM FRONT LH (SN)	CUT	300.00	300.00
			2,010.00	810.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT BUMPER TRD FRONT LIP.		750.00	500.00
	SPRAY PAINTING.		750.00	400.00
	STICKER WRAP.		750.00	600.00
			2,250.00	1,500.00
	GRAND TOTAL		6,781.50	4,831.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,850.00

Report Ref No. CS/SMO22003993/Avy3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.