

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003996/UEA3Q2**Date:** 05/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210015058
Claimant Vehicle No :	FBQ4514U	Insured Vehicle No :	SJZ378E
Date of Loss:	24/04/2022	Nature of Claim:	TP
		Claim No:	9499780602SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBQ4514U		
Make & Model:	YAMAHA AEROX GDR155A, 155cc CVT ABS	Engine No:	G3J8E0104998
Reg. Date:	08/10/2019 (Man. Year: 2019)	Chassis No:	MH3SG4640KJ055985
Colour:	Black	Odometer:	20391 km
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/80-14	Rear Tyre Size:	110/80-14
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,737.20	4,993.00	7,744.20	60.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	320.00	630.00	66.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,687.20	5,313.00	8,374.20	61.18
Approved Total (Overridden) (S\$)		4,250.00		
Nett Amount (S\$)	13,687.20	4,250.00	9,437.20	68.95
+ Loss of Use (6.0 x S\$20.00/day) (S\$)		120.00		
+ Other Costs (S\$)		50.00		
Nett Liability (S\$)		4,420.00		

INSPECTION

Date of Assignment:	28/04/2022	
Date Inspected:	28/04/2022 Inspected At:	Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ) 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK ASSY	Serviceable	980.00 FL	*- FL
2	1		*FORK UNDER BRACKET	Not Necessary	190.00 FL	*- FL
3	1		*FRONT SPORT RIM	Not Necessary	550.00 FL	*- FL
4	1		*FRONT BRAKE DISC	Not Necessary	180.00 FL	*- FL
5	1		*FRONT RIM SHAFT	Not Necessary	52.00 FL	*- FL
6	1		*FRONT RIM BEARING	Not Necessary	48.00 FL	*- FL
7	1		*HEADLAMP	Not Necessary	500.00 FL	*- FL
8	1		*SET SIDE MIRROR	Broken	120.00 FL	*120.00 FL
9	1		*HANDLE-BAR	Bent	135.00 FL	*135.00 FL
10	1		*SET HAND GRIP	Not Necessary	60.00 FL	*- FL
11	1		*BRAKE LEVER	N/S Cut / O/S NotNecessary	110.00 FL	*55.00 FL
12	1		*FRONT SIDE INNER COVER	Cut	210.00 FL	*195.00 FL
13	1		*RADIATOR COVER O/S	Torn	167.00 FL	*167.00 FL
14	2		*FOOTSTEP PANEL	Cut / Torn	510.00 FL	*510.00 FL
15	2		*FOOTSTEP PANEL LOWER COVER	Distorted	340.00 FL	*340.00 FL
16	1		*REAR FOOTREST	Cut	168.00 FL	*60.00 FL
17	1		*EXHAUST ASSY	Dented	680.00 FL	*680.00 FL
18	1		*EXHAUST PROTECTOR	Distorted	48.00 FL	*48.00 FL
19	1		*REAR SIGNALS N/S	Cut	180.00 FL	*90.00 FL
20	1		*SET FAIRING COVER	Cut	1,450.00 FL	*900.00 FL
21	1		*REAR RIM	Repair	680.00 FL	*- FL
22	1		*ENGINE COVER	Cracked	580.00 FL	*500.00 FL
23	1		*V BELT COVER	Cut	285.00 FL	*285.00 FL
24	1		*AIR FILTER COVER	Cut	125.00 FL	*125.00 FL
25	1		*RADIATOR	Dented / Punctured	620.00 FL	*480.00 FL
26	1		*SET NUMBER PLATE	Necessary	38.00 FS	*20.00 FS
27	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
28	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
29	1		*SET STEERING CONE	Not Necessary	120.00 FS	*- FS
30	1		*AEROX EMBLEM	Necessary	60.00 FS	*60.00 FS
31	1		*REAR BOX	Cut	3,810.00 FS	*300.00 FS
32	1		*REAR BOX BRACKET	Bent	180.00 FS	*120.00 FS
33	1		*E.R.P IU	Damaged	180.00 FS	*165.00 FS
34	1		*SET STICKER	Necessary	120.00 FS	*80.00 FS
35	1		*HANDLE-BAR BALANCER N/S	Cut	80.00 FL	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,642.00	5,465.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	904.80	472.00
Total Parts (\$\$)	12,737.20	4,993.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
2	TO RE-ALIGN BODY FRAME	New	450.00	0.00
3	TO PROVIDE LABOUR	New	420.00	320.00
Gross Labour Cost (\$)			950.00	320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >