

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22004001/EQCE2**Date:** 30/09/2022**REFERENCE**

Insured/Claimant: TAN YI TING Policy No: 1700094139-04
Date of Loss: 25/04/2022 Nature of Claim: OD Claim No: 4610375304SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV4371U**
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN045312
Reg. Date: 28/12/2017 (Man. Year: 2017) Chassis No: WAUZZZF41JA023310
Colour: White Odometer: 92719 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$103,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/40Z R18 Rear Tyre Size: 245/40Z R18
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,886.20	11,432.16	6,454.04	36.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,502.00	3,452.00	5,050.00	59.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,388.20	14,884.16	11,504.04	43.60
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	26,088.20	14,584.16	11,504.04	44.10
+ GST 7.00/7.00% (S\$)	1,826.17	1,020.89	805.28	44.10
Nett Amount (S\$)	27,914.37	15,605.05	12,309.32	44.10

INSPECTION

Date of Assignment: 28/04/2022
Date Inspected: 27/04/2022 Inspected At: 24 Benoi Sector Singapore 629857
Estimated Period of Repair: 5.0 days Repairer: Premium Automobiles Pte Ltd

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,688.80 FS	*1,688.80 FS
2	1		*FRONT BUMPER FIXING PARTS (NPA)	Not Necessary	0.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	O/S Bent	79.00 FS	*31.60 FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Broken	254.00 FS	*203.20 FS
6	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	72.00 FS	*- FS
7	1		*RADIATOR GRILLE	Not Necessary	1,277.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	151.00 FS	*- FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Broken	139.00 FS	*110.80 FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	899.00 FS	*719.20 FS
11	1		*FRONT BUMPER GUIDE SECTION - RH	Broken	41.00 FS	*32.24 FS
12	1		*FRONT BUMPER BRACKET - RH	Not Necessary	254.00 FS	*- FS
13	1		*FRONT BUMPER TOP COVER	Broken	143.00 FS	*114.00 FS
14	1		*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
15	1		*AIR COND STICKER	Necessary	9.00 FS	*6.64 FS
16	1		*FRONT BUMPER LOCK CARRIER BRACKET	Broken	154.00 FS	*122.80 FS
17	2		*FRONT BUMPER SUPPORT - LH / RH	Necessary	64.00 FS	*51.04 FS
18	4		*POP RIVET	Necessary	4.00 FS	*2.88 FS
19	1		*HORN - RH	Not Necessary	139.00 FS	*- FS
20	1		*HORN SUPPORT - RH	Not Necessary	33.00 FS	*- FS
21	1		*FRONT FENDER - RH	Dented	861.00 FS	*688.80 FS
22	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	211.00 FS	*- FS
23	1		*FRONT FENDER CLOSING ELEMENT - RH	Necessary	81.00 FS	*64.24 FS
24	1		*FRONT FENDER BRACKET - RH	Necessary	41.00 FS	*32.72 FS
25	1		*FRONT FENDER BRACE - RH	Dented	132.00 FS	*105.20 FS
26	1		*FRONT FENDER BRACKET CENTER - RH	Not Necessary	55.00 FS	*- FS
27	1		*FRONT WHEEL HOUSING LINER - RH	Torn	262.00 FS	*209.60 FS
28	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS (NPA)	Not Necessary	0.00 FS	*- FS
29	1		*FRONT WHEEL SPOILER	Broken	82.00 FS	*65.12 FS
30	1		*FRONT WHEEL SPOILER LOWER - RH	Not Necessary	40.00 FS	*- FS
31	1		*FRONT WHEEL SPOILER STONE CHIP GUARD - RH	Not Necessary	57.00 FS	*- FS
32	1		*FRONT FENDER LEDGE COVER LONG - RH	Not Necessary	35.00 FS	*- FS
33	1		*FRONT FENDER LEDGE COVER SHORT - RH	Broken	26.00 FS	*20.16 FS
34	1		*HEADLIGHT - RH	Broken	6,154.40 FS	*6,154.40 FS
35	1		*HEADLIGHT POWER MODULE	Broken	840.00 FS	*672.00 FS
36	1		*HEADLIGHT CONTROL UNIT	Not Necessary	840.00 FS	*- FS
37	1		*HEADLIGHT HOSE - RH	Not Necessary	42.00 FS	*- FS
38	3		*SPACER	Not Necessary	136.00 FS	*- FS
39	1		*LIFT CYLINDER - RH	Broken	231.00 FS	*184.40 FS
40	1		*LIFT CYLINDER BRACKET	Broken	7.00 FS	*5.44 FS
41	1		*LIFT CYLINDER CORRUGATED PIPE	Torn	107.00 FS	*85.60 FS
42	1		*LIFT CYLINDER HOSE - INNER	Not Necessary	45.00 FS	*- FS
43	1		*LOCK CARRIER	Not Necessary	1,127.00 FS	*- FS
44	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Necessary	21.00 FS	*16.32 FS
45	6		*RADIATOR COOLANT	Not Necessary	282.00 FS	*- FS
46	1		*RADIATOR AIR GUIDE INNER - RH	Not Necessary	32.00 FS	*- FS
47	1		*RADIATOR AIR GUIDE OUTER - RH	Not Necessary	14.00 FS	*- FS
48	1		*RADIATOR AIR GUIDE UPPER	Not Necessary	19.00 FS	*- FS
49	1		*FRONT NO PLATE	Not Necessary	120.00 FS	*- FS
50	1		*SUNDRIES	Necessary	350.00 FS	*32.56 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 17,886.20 11,432.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS	New	1,400.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,200.00	1,000.00
5	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,650.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			8,502.00	3,452.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >