

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/III22004004/UPA3Q2**Date:** 20/06/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549\_02

**Claimant Vehicle No :** SJT2507T **Insured Vehicle No :** YQ135J

Date of Loss: 27/04/2022 Nature of Claim: TP Claim No: MFL2022D0002220

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJT2507T**  
 Make & Model: KIA CERATO FORTE, 1.6 A/T ABS AB 2WD 4DR (A) Engine No: G4FC9H297939  
 Reg. Date: 30/09/2009 (Man. Year: 2009) Chassis No: KNAFU411MA5130405  
 Colour: Grey Odometer: 153080 km  
 Engine Capacity: 1591 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17  
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	712.00	80.00	632.00	88.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	1,250.00	300.00	19.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,262.00</b>	<b>1,330.00</b>	<b>932.00</b>	<b>41.20</b>
<b>+ GST 7.00/7.00% (S\$)</b>	158.34	93.10	65.24	41.20
<b>Nett Amount (S\$)</b>	<b>2,420.34</b>	<b>1,423.10</b>	<b>997.24</b>	<b>41.20</b>
<b>+ Car Rental (3.0 x S\$100.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>1,730.55</b>		

INSPECTION

Date of Assignment: 05/05/2022

Date Inspected: 05/05/2022 Inspected At:

Estimated Period of Repair: 3.0 days

Hock Wah Motor Workshop Pte Ltd (Bedok)  
 Blk 3011, Bedok Industrial Park E,, #01-  
 2008/2010/2012  
 Singapore 489977

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG    Version: 1.0 (Last Synchronised: 02 Jun 2022)

**Parts:** 143    KIA CERATO FORTE 1.6 A/T ABS AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's    (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJT2507T)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Repair	632.00 F	*- F
2	1		*REAR FENDER LH (NPA)	Repair	0.00 FS	*- FS
3	1		*REAR BUMPER (NPA)	Repair	0.00 FS	*- FS
4	1		*FRONT DOOR LH (NPA)	Repair	0.00 FS	*- FS
5	1		*SET N/S DOOR VISOR	Cracked / Necessary	80.00 FS	*80.00 FS
					<b>Total Parts (\$\$)</b>	<b>712.00    80.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	600.00	500.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	750.00
3	ANTI-RUST COATING	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,550.00</b>	<b>1,250.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >