

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004009/UVY3M4**Date:** 02/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00063742101		
Claimant Vehicle No :	FBN1601L	Insured Vehicle No :	GBH678D		
Date of Loss:	14/04/2022	Nature of Claim:	TP	Claim No:	SNM22D202872/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN1601L		
Make & Model:	YAMAHA NMAX155, 155cc ABS	Engine No:	G3H6E0009654
Reg. Date:	25/07/2018 (Man. Year: 2018)	Chassis No:	MH3SG431000007455
Colour:	White	Odometer:	65449 km
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70-13	Rear Tyre Size:	130/70-13
Front Left Side:	Timsun 6 mm	Rear Left Side:	Timsun 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,244.00	1,045.40	198.60	15.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	472.00	415.00	57.00	12.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,716.00	1,460.40	255.60	14.90
Approved Total (Overridden) (S\$)		1,150.00		
(S\$)	1,716.00	1,150.00	566.00	32.98
+ GST 7.00/7.00% (S\$)	120.12	80.50	39.62	32.98
Nett Amount (S\$)	1,836.12	1,230.50	605.62	32.98

INSPECTION

Date of Assignment:	28/04/2022		
Date Inspected:	29/04/2022	Inspected At:	BAN HOCK HIN CO.PTE LTD (HQ) NO. 6 DEFU LANE 4 SINGAPORE 539410
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Jun 2022)	
Parts:	N/A	YAMAHA NMAX155 155cc ABS (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN1601L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BELLY PAN	Cut	35.00 F	*35.00 FL
2	1		*BOARD FOOTREST RH	Cut	55.00 F	*55.00 FL
3	1		*BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT	Cut	222.00 F	*222.00 FL
4	1		*BRACKET MASTER CYLINDER RH	Cracked	10.00 F	*10.00 FL
5	1		*COVER SIDE LOWER RH (WHITE)	Cut	22.00 F	*22.00 FL
6	1		*COVER SIDE RH (SILVER)	Cut	38.00 F	*38.00 FL
7	1		*COWLING FRONT RH (WHITE)	Cut	35.00 F	*35.00 FL
8	1		*DAMPER PLATE	Distorted	30.00 F	*30.00 FL
9	1		*EMBLEM (YAMAHA) LOGO	Necessary	15.00 F	*15.00 FL
10	1		*ENGINE BRACKET COMP	Not Necessary	70.00 F	*- FL
11	1		*GASKET EXHAUST PIPE	Necessary	12.00 F	*12.00 FL
12	1		*LEVER BRAKE RH	Cut	18.00 F	*18.00 FL
13	1		*MIRROR RH	Broken	38.00 F	*38.00 FL
14	1		*MUDGUARD REAR	Distorted	52.00 F	*52.00 FL
15	1		*PANEL 2 (GREY) RH	Cut	22.00 F	*22.00 FL
16	1		*PIPE EXHAUST ASSY	Dented	407.00 F	*407.00 FL
17	1		*PROTECTOR EXHAUST	Cut	38.00 F	*38.00 FL
18	1		*REFLECTOR ASSY REAR	Cracked	15.00 F	*15.00 FL
19	2		*RIVET	Necessary	6.00 F	*6.00 FL
20	1		*STICKER (CISCO) COVER CENTRE RH	Necessary	38.00 F	*38.00 FL
21	1		*STICKER (CISCO) COWLING FRONT RH	Necessary	38.00 F	*38.00 FL
22	1		*PLATE NUMBER REAR (6.5 INCH X 9 INCH)	Bent	28.00 FS	*14.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,244.00	1,160.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	114.60
Total Parts (\$\$)	1,244.00	1,045.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	New	252.00	240.00
2	SPRAY LACQUER ON COVER SIDE RH.	New	90.00	70.00
3	SPRAY LACQUER ON COWLING FRONT RH.	New	90.00	70.00
4	TRANSPORT CHARGES (BIKE TOWED BACK TO BHH)	New	40.00	35.00
Gross Labour Cost (\$\$)			472.00	415.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >