

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC22004010/Rqy3e2	
	300 BEACH ROAD SINGAPORE 1995	#17-04/07 THE CONCOURSE 55		Date:	11/05/2022	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XD 3129M	Veh. Inspected		SLE 6056G	
	Policy No.	Z/21/VC06/112962	Coverage (\$)		0.00	
	Claim No.	21/22/22/VC06/025729	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		28/04/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA SHUTTLE 1.5G CVT	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	GK81004867	Colour		WHITE	
	Odometer	145969 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/55R15	MICHELIN		6 mm	
	L/H Front Tyre	195/55R15	MICHELIN		6 mm	
	R/H Rear Tyre	195/55R15	MICHELIN		6 mm	
	L/H Rear Tyre	195/55R15	MICHELIN		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S REAR BODY.				
5.	General Information					
	Accident Date	27/04/2022	Inspect Date /	Time	28/04/2022 (03:51 PM)	
	Survey held at	ld at GARAGE 13 PTE LTD				
		8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22004010/Rqy3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE