

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22004012/UVY3M4**Date:** 12/07/2022**REFERENCE**

Insured/Claimant: ANG HONG @ HONG HAO Policy No: DMPCSNW00231892101

Date of Loss: 25/04/2022

Nature of Claim: OD

Claim No: SNM22D202834/C01/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF7919T	Engine No:	HR12232415J
Make & Model:	NISSAN NOTE, 1.2 (A)	Chassis No:	JN1TAAE12Z0982396
Reg. Date:	26/11/2018 (Man. Year: 2018)	Odometer:	79832 km
Colour:	Blue		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	S\$60,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,379.36	2,539.20	1,840.16	42.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,285.00	2,485.00	800.00	24.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,664.36	5,024.20	2,640.16	34.45
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	7,164.36	4,524.20	2,640.16	36.85
+ GST 7.00/7.00% (S\$)	501.51	316.69	184.82	36.85
Nett Amount (S\$)	7,665.87	4,840.89	2,824.98	36.85

INSPECTION

Date of Assignment: 28/04/2022

Date Inspected: 29/04/2022

Inspected At:

Autolution Industrial Pte Ltd (Ubi)
19 Ubi Road 4
Singapore 408623

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jul 2022)
Parts:	144	NISSAN NOTE 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF7919T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR COMB LAMP LH	Not Necessary	470.60 FN	*- FN
2	1		*REAR COMB LAMP RH	Not Necessary	470.60 FN	*- FN
3	1		*TAIL GATE INTERIOR FINISHER	Not Necessary	142.50 FN	*- FN
4	1		*REAR PANEL	Badly Dented	597.60 FN	*597.60 FN
5	1		*BOX-LUGGAGE REAR	Not Necessary	154.40 FN	*- FN
6	1		*CARPET-LUGGAGE FLOOR	Not Necessary	468.60 FN	*- FN
7	1		*TRUNK TOP PLATE	Deformed	74.30 FN	*74.30 FN
8	1		*EMBLEM REAR NOTE	Necessary	86.20 FN	*86.20 FN
9	1		*EMBLEM-REAR NISSAN	Necessary	70.00 FN	*70.00 FN
10	1		*STRIKER-TAIL GATE	Not Necessary	37.60 FN	*- FN
11	1		*TAIL GATE DOOR LOCK	Dented	138.50 FN	*138.50 FN
12	1		*REAR W/SCREEN CORNER MLDG LH	Necessary	33.90 FN	*33.90 FN
13	1		*REAR W/SCREEN CORNER MLDG RH	Necessary	33.90 FN	*33.90 FN
14	1		*REAR W/SCREEN GLASS MLDG	Necessary	75.10 FN	*75.10 FN
15	1		*TAIL GATE W/STRIP	Not Necessary	73.60 FN	*- FN
16	1		*TAIL GATE BACK DOOR	Dented	1,099.10 FN	*1,099.10 FN
17	2		*REAR BUMPER STAY @\$104.70 EACH	Not Necessary	209.40 FN	*- FN
18	1		*ENERGY ABSORBER REAR BUMPER	Not Necessary	135.40 FN	*- FN
19	1		*REAR BUMPER SIDE BRKT LH	Bent	52.30 FN	*52.30 FN
20	1		*REAR BUMPER SIDE BRKT RH	Bent	52.30 FN	*52.30 FN
21	10		*CLIP REAR BUMPER @\$1.40 EACH	Necessary	14.00 FN	*14.00 FN
22	1		*REAR BUMPER FASCIA	Torn	496.80 FN	*496.80 FN
23	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
24	1		*REAR LICENCE PLATE	Serviceable	60.00 FS	*- FS
25	1		*REAR W/SCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
26	1		*SENSOR-REVERSE	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	5,376.70	3,104.00
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	997.34	564.80
Total Parts (\$\$)	4,379.36	2,539.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOR CHARGES TO REPAIR TRUNK FLOOR, BOTH REAR FENDER, RENEW REAR PANEL, TAIL GATE & REAR BUMPER	New	1,400.00	980.00
2	CHARGES TO SPRAY PAINTING SAME	New	1,350.00	1,000.00
3	REMOVE AND INSTALL REAR W/SCREEN GLASS	New	180.00	150.00
4	REMOVE AND INSTALL TAIL GATE DOOR MECHANISM	New	80.00	80.00
5	APPLY SEALANT TO TAIL GATE BACK DOOR	New	100.00	100.00
6	PERFORM RUST PROODFNG TO REAR PANEL	New	120.00	120.00
7	REMOVE AND INSTALL REVERSE SENSOR - RENEW IF NEC RESET AND FUNCTION TEST	New	55.00	55.00
8	RENEW REAR LICENCE PLATE (NPA)	New	0.00	0.00
Gross Labour Cost (\$\$)			3,285.00	2,485.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >