

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III22004014/RPA3Q2
Date: 20/10/2022

REFERENCE

| | | | |
|------------------------------|---------------------------------------|-----------------------------|---------------------------|
| Handling Insurer: | India International Insurance Pte Ltd | Policy No: | D20MFL0004693_01 |
| Claimant Vehicle No : | SHA1013G | Insured Vehicle No : | SNA5243L |
| Date of Loss: | 25/04/2022 | Nature of Claim: | TP |
| | | | Claim No: MFL2022D0002162 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|---------------------------------------|-------------|-------------------|
| Reg No: | SHA1013G | Engine No: | G4LEJU045446 |
| Make & Model: | HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) | Chassis No: | KMHC851CVJU103305 |
| Reg. Date: | 29/06/2018 (Man. Year: 2018) | Odometer: | 0 km |
| Colour: | Blue | | |
| Engine Capacity: | 1580 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|----------------|------------------|----------------|
| Front Tyre Size: | 195/65 R15 | Rear Tyre Size: | 195/65 R15 |
| Front Left Side: | West Lake 6 mm | Rear Left Side: | West Lake 6 mm |
| Front Right Side: | West Lake 6 mm | Rear Right Side: | West Lake 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-----------------|-----------------|-----------------|--------------|
| Parts | 4,572.40 | 1,550.24 | 3,022.16 | 66.10 |
| Miscellaneous Items | 11.00 | 11.00 | 0.00 | 0.00 |
| Labour | 1,600.00 | 1,065.00 | 535.00 | 33.44 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 6,183.40 | 2,626.24 | 3,557.16 | 57.53 |
| Approved Total (Overridden) (S\$) | | 2,050.00 | | |
| (S\$) | 6,183.40 | 2,050.00 | 4,133.40 | 66.85 |
| + GST 7.00/7.00% (S\$) | 432.84 | 143.50 | 289.34 | 66.85 |
| Nett Amount (S\$) | 6,616.24 | 2,193.50 | 4,422.74 | 66.85 |
| + Loss of Use (4.0 x S\$40.00/day) (S\$) | | 160.00 | | |
| + Car Rental (4.0 x S\$125.19/day) (S\$) | | 500.76 | | |
| + Doc/Search Fee (S\$) | | 7.49 | | |
| Nett Liability (S\$) | | 2,861.75 | | |

INSPECTION

| | | | |
|-----------------------------|------------|-------------------|--|
| Date of Assignment: | 27/04/2022 | Present Location: | ComfortDelGro Engineering Pte Ltd (Loyang) ComfortDelGro Engineering Pte Ltd (Loyang) |
| Date Inspected: | 27/04/2022 | Inspected At: | 59 Loyang Drive Singapore 508969 |
| Estimated Period of Repair: | 4.0 days | | |

Adjuster: MOHD RASUL

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 21 Jun 2022)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SHA1013G)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------------|---------------|-------------|------------|
| 1 | 1 | | *REAR BUMPER COVER | Cracked | 459.40 FL | *459.40 FL |
| 2 | 1 | | *REAR BUMPER CLIPS | Necessary | 22.00 FL | *22.00 FL |
| 3 | 1 | | *REAR BUMPER CENTRE MOULDING ASSY | Scratched | 451.25 FL | *451.25 FL |
| 4 | 1 | | *REAR BUMPER REINFORCEMENT | Not Necessary | 394.80 FL | *- FL |
| 5 | 1 | | *REAR BUMPER REINFORCEMENT BRACKET LH | Not Necessary | 138.10 FL | *- FL |
| 6 | 1 | | *REAR BUMPER REINFORCEMENT BRACKET RH | Not Necessary | 138.10 FL | *- FL |
| 7 | 1 | | *REAR BUMPER FOG LAMP | Scratched | 201.50 FL | *201.50 FL |
| 8 | 1 | | *REAR BUMPER LICENCE LAMP | Not Necessary | 85.30 FL | *- FL |
| 9 | 1 | | *ANTENNA ASSY SMARTKEY | Not Necessary | 40.50 FL | *- FL |
| 10 | 1 | | *REAR BUMPER TOWING COVER | Not Necessary | 94.60 FL | *- FL |
| 11 | 1 | | *REAR BUMPER SIDE BRACKET LH | Not Necessary | 55.80 FL | *- FL |
| 12 | 1 | | *REAR BUMPER SIDE BRACKET RH | Not Necessary | 55.80 FL | *- FL |
| 13 | 1 | | *REAR BUMPER LOWER CTR MOULDING | Scratched | 155.00 FL | *155.00 FL |
| 14 | 1 | | *BOOTLID | Repair | 2,549.70 FL | *- FL |
| 15 | 1 | | *BOOTLID HYUNDAI PLATE | Necessary | 24.30 FL | *24.30 FL |
| 16 | 1 | | *EMBLEM HYBRID | Necessary | 24.30 FL | *24.30 FL |
| 17 | 1 | | *EMBLEM – IONIQ | Necessary | 31.30 FL | *31.30 FL |
| 18 | 1 | | *REAR FENDER ADVERTISEMENT STICKER LH | Necessary | 100.00 F | *100.00 F |
| 19 | 1 | | *REAR FENDER ADVERTISEMENT STICKER RH | Necessary | 100.00 F | *100.00 F |
| 20 | 1 | | *BOOTLID ADVERTISEMENT STICKER | Necessary | 100.00 F | *100.00 F |
| 21 | 1 | | *REAR NUMBER PLATE WITH TRIM COVER | Cracked | 55.00 F | *55.00 F |
| 22 | 1 | | *BOOTLID COMFORT TEL NO STICKER | Necessary | 40.00 F | *40.00 F |
| 23 | 1 | | *BOOTLID COMFORT LOGO STICKER | Necessary | 30.00 F | *30.00 F |
| 24 | 1 | | *BOOTLID COMFORT APP STICKER | Necessary | 30.00 F | *30.00 F |
| 25 | 1 | | *REAR BUMPER REVERSE SENSOR | Not Necessary | 180.00 F | *- F |

F=Franchise part. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$) | 5,556.75 | 1,824.05 |
| - List Item Discount on L Items 20.00/20.00% (\$) | 984.35 | 273.81 |
| Total Parts (\$) | 4,572.40 | 1,550.24 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

| No | Qty | Particulars | Repairer's | Amount |
|----------------------------|-----|----------------------|-----------------------|--------------|
| Miscellaneous Items | | | | |
| 1 | 1 | OD/TP Case (Insurer) | 11.00 | 11.00 |
| | | | Sub Total (\$) | 11.00 |

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|-----------------------------|----------|-------------------------------|-----------------|
| Labour Items | | | | |
| 1 | PANEL BEATING | New | 800.00 | 525.00 |
| 2 | SPRAY PAINTING CHARGE | New | 600.00 | 500.00 |
| 3 | CHK ALL LIGHTING | New | 60.00 | 0.00 |
| 4 | TUFF KOTE | New | 60.00 | 0.00 |
| 5 | REMOVE/REFIX REVERSE SENSOR | New | 80.00 | 40.00 |
| | | | Gross Labour Cost (\$) | 1,600.00 |
| | | | | 1,065.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >