

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22004015/AQY3E2

Date: 04/08/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00104562200
Claimant Vehicle No: SLW3725J Insured Vehicle No: SNF8108Z
Date of Loss: 28/04/2022 Nature of Claim: TP Claim No: SNM22D202877/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLW3725J
Make & Model: KIA FORTE K3, 1.6 (A) Engine No: G4FGHH688202
Reg. Date: 09/02/2018 (Man. Year: 2017) Chassis No: KNAFJ411MJ5756377
Colour: White Odometer: 90733 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm
Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,679.00	7,767.60	4,911.40	38.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,930.00	2,730.00	1,200.00	30.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,609.00	10,497.60	6,111.40	36.80
Approved Total (Overridden) (\$\$)		8,400.00		
Nett Amount (\$\$)	16,609.00	8,400.00	8,209.00	49.43

INSPECTION

Date of Assignment: 29/04/2022
Date Inspected: 29/04/2022 Inspected At: Automobile Hub Enterprise
1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT
Singapore 417883
Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Aug 2022)
Parts:	143	KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW3725J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
2	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
3	1		*REAR BUMPER	Distorted	688.00 F	*688.00 FL
4	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
5	2		*REAR BUMPER SIDE HOLDER	Damaged	110.00 F	*110.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Distorted	318.00 F	*318.00 FL
7	2		*REAR BUMPER REINFORCEMENT STAY	Dented	218.00 F	*218.00 FL
8	1		*REAR BUMPER LOWER GARNISH	Distorted	383.00 F	*383.00 FL
9	2		*REAR BUMPER LOWER GARNISH REFLECTOR	Cracked	142.00 F	*142.00 FL
10	1		*REAR END PANEL	Distorted	349.00 F	*349.00 FL
11	1		*REAR END PANEL TOP GARNISH	Cracked	149.00 F	*149.00 FL
12	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
13	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
14	2		*TAILLAMP	Cracked	1,216.00 F	*1,216.00 FL
15	2		*TAILLAMP SIDE GARNISH	Cracked	50.00 F	*50.00 FL
16	2		*TAILLAMP PANEL	Dented	488.00 F	*488.00 FL
17	1		*BOOTLID	Distorted	1,297.00 F	*1,297.00 FL
18	1		*BOOTLID LOCK	Damaged	288.00 F	*288.00 FL
19	1		*BOOTLID WEATHERSTRIPE	Cut	168.00 F	*168.00 FL
20	2		*BOOTLID HINGE	Bent	198.00 F	*198.00 FL
21	1		*BOOTLID INNER TRIM COVER	Torn	242.00 F	*242.00 FL
22	1		*BOOTLID INNER TRIM COVER CLIPS	Necessary	30.00 FS	*30.00 FS
23	2		*BOOTLID REFLECTOR	Cracked	934.00 F	*934.00 FL
24	1		*KIA LOGO	Necessary	45.00 F	*45.00 FL
25	1		*CERATO WORDING	Necessary	48.00 F	*48.00 FL
26	1		*K3 WORDING	Necessary	42.00 F	*42.00 FL
27	1		*CYCLE AND CARRIAGE LOGO	Necessary	38.00 FS	*38.00 FS
28	1		*REAR CAMERA	Not Necessary	450.00 FS	*- FS
29	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
30	2		*REAR FENDER	Repair	2,366.00 F	*- FL
31	2		*REAR FENDER INNER TRIM BOARD	Torn	516.00 F	*516.00 FL
32	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*60.00 FS
33	1		*SPARE TYRE PANEL TOP COVER	Cracked	255.00 F	*255.00 FL
34	1		*REAR EXHAUST PIPE	Not Necessary	825.00 F	*- FL
35	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	39.00 F	*- FL
36	1		*REAR EXHAUST PIPE GASKET	Not Necessary	35.00 F	*- FL
37	1		*REAR WINDSCREEN MOULDING	Not Necessary	182.00 F	*- FL
38	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,679.00	8,582.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	814.40
Total Parts (S\$)	12,679.00	7,767.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,600.00	1,200.00
2	SPRAY PAINTING	New	1,400.00	1,200.00
3	WIRING	New	100.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	80.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE REAR CAMERA	New	100.00	50.00
7	TO REMOVE UPHOLSTERY	New	150.00	60.00
8	TO TRANSFER BOOTLID FITTINGS	New	150.00	60.00
9	TO REMOVE REAR WINDSCREEN	New	180.00	0.00
Gross Labour Cost (S\$)			3,930.00	2,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >