



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2203540

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 09/06/2022  
Reference CC3/CTI22004019/Kpa3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SHD 145A  
Insured Veh. GBD 2236D  
Claim No. SNM22D202892/C02  
Policy No. DMCVSNW00073452100  
Accident Date 26/04/2022  
Inspection Date 27/04/2022

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC3/CTI22004019/Kpa3q2	
			Date: 09/06/2022	
			Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBD 2236D	Veh. Inspected	SHD 145A	
Policy No.	DMCVSNW00073452100	Coverage (\$)	0.00	
Claim No.	SNM22D202892/C02	Excess (\$)	0.00	
Assign From		Assign Date	27/04/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	VF1ABL15AUC282250	Colour	METALLIC WHITE/RED	
Odometer	302546 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	SAILUN	7 mm	
L/H Front Tyre	215/60 R16	SAILUN	7 mm	
R/H Rear Tyre	215/60 R16	SAILUN	8 mm	
L/H Rear Tyre	215/60 R16	SAILUN	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	26/04/2022	Inspection Date	27/04/2022	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 145A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	DOOR PANEL FRT LH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR HINGE UPPER FRT LH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER FRT LH	TO REPAIR SEE LABOUR	300.55	-
1	ROCKER PANEL OUTER LH	TO REPAIR SEE LABOUR	1,184.99	-
1	FENDER PANEL INNER FRT LH	TO REPAIR SEE LABOUR	858.30	-
1	FENDER PANEL FRT LH	BENT	437.10	437.10
1	WHEELARCH FRT LH	CRACKED	191.40	191.40
1	BUMPER COVER FRT	CRACKED	747.20	747.20
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	663.70	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT LH	CRACKED	101.40	101.40
1	BUMPER SPOILER FRT	DISTORTED	344.70	344.70
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	147.00	-
1	BUMPER FOG LAMP GRILLE LH	DISTORTED	207.21	207.21
1	BONNET	BENT	1,312.70	1,312.70
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	237.40	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	237.40	-
1	AIR CLEANER LOWER	SERVICEABLE	271.26	-
1	AIR CLEANER HOSE	SERVICEABLE	175.85	-
1	AIR CLEANER BOX	SERVICEABLE	464.20	-
1	RADIATOR GRILLE	CRACKED	969.90	969.90
1	RADIATOR GRILLE BADGE 'RENAULT'	NECESSARY	225.36	225.36
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	592.70	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	686.00	-
1	HEADLAMP LH	BROKEN	743.60	743.60

Report Ref No. CC3/CTI22004019/Kpa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	128.30	-
	LESS 10% DISCOUNT		-1,474.21	-528.06
			13,267.85	4,752.51
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	DOOR TRIM CLIP (SN)	NOT NECESSARY	70.00	-
1	DOOR MOULDING CLIP (SN)	NOT NECESSARY	70.00	-
1	DOOR STICKER TRANSCAB (SN)	NOT NECESSARY	100.00	-
1	FRONT DOOR ADVERTISEMENT (SN)	NOT NECESSARY	200.00	-
1	DOOR STICKER CLASSIC (SN)	NOT NECESSARY	100.00	-
1	FRT BUMPER CLIP (SN)	NECESSARY	65.00	65.00
1	FENDER CLIP (SN)	NECESSARY	70.00	70.00
1	FENDER LINER CLIP (SN)	NOT NECESSARY	65.00	-
			740.00	135.00
	<b><u>LABOUR</u></b>			
	TO RUST PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS .		230.00	60.00
	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		1,400.00	880.00
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR PANEL FRT LH,DOOR HINGE UPPER FRT LH,DOOR HINGE LOWER FRT LH,ROCKER PANEL OUTER LH,FENDER PANEL INNER FRT LH,BUMPER BEAM FRT,BONNET HINGE LH, BONNET HINGE RH AND HEADLAMP PANEL FRT LH.		2,000.00	500.00
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO CHECK STEERING AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			4,360.00	1,460.00
<b>GRAND TOTAL</b>			<b>18,367.85</b>	<b>6,347.51</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>5,100.00</b>
---	--	--	-----------------

Report Ref No. CC3/CTI22004019/Kpa3q2

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHD 145A

### INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

