

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22004020/EVY3E2**Date:** 21/02/2023REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No : SLL1780U**Insured Vehicle No :** SMJ3225S

Date of Loss: 26/04/2022

Nature of Claim:

TP

Claim No: DMPC2200177H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLL1780U**

Make & Model: VOLKSWAGEN CADDY, 1.4 MAXI TSI AT SAJHK5 (A)

Engine No: CZC640111

Reg. Date: 16/02/2017 (Man. Year: 2016)

Chassis No: WV2ZZZ2KZHX070933

Colour: Grey

Odometer: 111442 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size:

225/45 R17

Front Left Side: Dunlop 5 mm

Rear Left Side:

Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side:

Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,508.00	10,555.20	20,952.80	66.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,250.00	7,650.00	4,600.00	37.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	43,758.00	18,205.20	25,552.80	58.40
+ GST 8.00/8.00% (S\$)	3,500.64	1,456.42	2,044.22	58.40
Nett Amount (S\$)	47,258.64	19,661.62	27,597.02	58.40

INSPECTION

Date of Assignment: 28/04/2022

Date Inspected: 05/05/2022

Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 14.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Feb 2023)	
Parts:	N/A	VOLKSWAGEN CADDY 1.4 MAXI TSI AT SAJHK5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL1780U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Repair	1,560.00 FS	*- FS
2	2	*FRONT BUMPER SUPPORT ELEMENT - LH / RH	Not Necessary	556.00 FS	*- FS
3	8	*LOCKING CLIP	Not Necessary	35.00 FS	*- FS
4	1	*FRONT BUMPER ATTACHMENT PARTS	Not Necessary	13.00 FS	*- FS
5	1	*FRONT BUMPER SPOILER	Not Necessary	679.00 FS	*- FS
6	1	*FRONT BUMPER TOWING EYE	Not Necessary	68.00 FS	*- FS
7	2	*FRONT BUMPER GUIDE FRAME - LH / RH	Not Necessary	88.00 FS	*- FS
8	1	*RADIATOR GRILLE	Not Necessary	580.00 FS	*- FS
9	1	*VW EMBLEM	Not Necessary	139.00 FS	*- FS
10	1	*RADIATOR GRILLE VENT	Cut	361.00 FS	*361.00 FS
11	1	*FRONT BUMPER CHROME TRIM	Not Necessary	318.00 FS	*- FS
12	2	*FRONT BUMPER FOG LAMPS COVER - LH / RH	Not Necessary	332.00 FS	*- FS
13	2	*FRONT BUMPER FOG LAMPS TRIM - LH / RH	Not Necessary	170.00 FS	*- FS
14	2	*FRONT BUMPER GUIDE PROFILE - LH / RH	Not Necessary	186.00 FS	*- FS
15	1	*FRONT BUMPER FOAM FILLER PIECE - LOWER	Not Necessary	95.00 FS	*- FS
16	1	*FRONT BUMPER FOAM FILLER PIECE - CENTER	Not Necessary	102.00 FS	*- FS
17	1	*FRONT BUMPER CROSS MEMBER - LOWER	Not Necessary	330.00 FS	*- FS
18	1	*FRONT BUMPER SIDE REINFORCEMENT	Not Necessary	953.00 FS	*- FS
19	1	*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	6.00 FS	*- FS
20	1	*LOCK CARRIER SUPPORT - CENTER	Not Necessary	158.00 FS	*- FS
21	2	*HEADLIGHT - LH / RH	Not Necessary	5,572.00 FS	*- FS
22	2	*FOG LAMPS - LH / RH	Not Necessary	654.00 FS	*- FS
23	2	*RADIATOR AIR GUIDE INNER - LH / RH	Not Necessary	62.00 FS	*- FS
24	1	*REAR BUMPER	Broken	1,086.00 FS	*1,086.00 FS
25	1	*REAR BUMPER FIXING PARTS	Not Necessary	51.00 FS	*- FS
26	1	*REAR BUMPER TOW HITCH COVER CAP	Not Necessary	76.00 FS	*- FS
27	1	*REAR BUMPER LOWER	Dented	1,022.00 FS	*1,022.00 FS
28	1	*REAR GUIDE PROFILE - LH / RH	N/S Broken	98.00 FS	*49.00 FS
29	1	*REAR PARKING AID SENSOR BRACKET	Necessary	124.00 FS	*124.00 FS
30	2	*REAR PARKING AID SENSOR - CENTER	Not Necessary	530.00 FS	*- FS
31	2	*REAR PARKING AID SENSOR - LH	Not Necessary	530.00 FS	*- FS
32	4	*REAR PARKING AID SENSOR CAP	Necessary	47.00 FS	*47.00 FS
33	4	*REAR PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
34	1	*SET REAR BUMPER WIRING	Not Necessary	464.00 FS	*- FS
35	2	*TAIL LIGHT - LH / RH	Broken	636.00 FS	*636.00 FS
36	1	*REAR LIGHT REFLECTOR - LH / RH	N/S Broken	156.00 FS	*78.00 FS
37	2	*LICENCE PLATE LIGHT	Not Necessary	219.00 FS	*- FS
38	1	*REAR LID	Dented	3,510.00 FS	*3,510.00 FS
39	1	*ANTI CORROSION WAX	Not Necessary	51.00 FS	*- FS
40	1	*REAR LID SEAL	Torn	251.00 FS	*251.00 FS
41	1	*REAR LID LOOP	Not Necessary	144.00 FS	*- FS
42	1	*REAR LID LOCK ACTUATOR WITH CAMERA	Not Necessary	1,340.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
43	1	*REAR LID LOCK MICROSWITCH	Bent	109.00 FS	*109.00 FS
44	1	*REAR LID LOCK ACTUATOR WITH CAMERA COVER	Not Necessary	26.00 FS	*- FS
45	1	*REAR LID STRIKER PLATE	Bent	66.00 FS	*66.00 FS
46	2	*REAR LID GUIDE SECTION	Not Necessary	82.00 FS	*- FS
47	2	*BONNET ABSORBER	Not Necessary	273.00 FS	*- FS
48	2	*REAR LID HINGE (NPA)	Not Necessary	0.00 FS	*- FS
49	1	*CADDY EMBLEM	Necessary	81.00 FS	*81.00 FS
50	1	*VW EMBLEM	Necessary	114.00 FS	*114.00 FS
51	1	*TSI EMBLEM	Necessary	100.00 FS	*100.00 FS
52	1	*REAR LID TRIM - CENTER	Broken	489.00 FS	*489.00 FS
53	1	*REAR LID LOAD EDGE PROTECTION	Not Necessary	414.00 FS	*- FS
54	1	*REAR WINDSCREEN (BROKEN)	Not Consistent With The Impact	875.00 FS	*- FS
55	1	*SET 2K PANE ADHESIVE	Not Necessary	105.00 FS	*- FS
56	1	*PRIMER	Not Necessary	22.00 FS	*- FS
57	1	*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
58	1	*APPLICATOR ADHESIVE	Not Necessary	8.00 FS	*- FS
59	1	*APPLICATOR	Not Necessary	6.00 FS	*- FS
60	1	*ACTIVATOR	Not Necessary	19.00 FS	*- FS
61	1	*REAR END PANEL	Dented	471.00 FS	*471.00 FS
62	1	*REAR END PANEL LOCK CARRIER - CENTER	Dented	184.00 FS	*184.00 FS
63	1	*REAR END PANEL LOCK CARRIER - LH / RH (2PCS)	Dented (1Pc Only)	170.00 FS	*85.00 FS
64	1	*TAIL LIGHT MOUNTING - LH	Not Necessary	84.00 FS	*- FS
65	1	*REAR LID TRIM PANEL	Not Necessary	93.00 FS	*- FS
66	1	*LUGGAGE COMPARTMENT COVER	Not Necessary	717.00 FS	*- FS
67	1	*REAR END PANEL UPPER TRIM	Broken	224.00 FS	*224.00 FS
68	1	*FLOORING - CENTER	Not Necessary	1,236.00 FS	*- FS
69	1	*REAR SILENCER	Not Necessary	183.00 FS	*- FS
70	1	*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
71	1	*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
72	1	*STONE CHIP	Necessary	180.00 FS	*180.00 FS
73	1	*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
74	1	*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
75	1	*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
76	1	*REAR NO PLATE	Bent	60.00 FS	*60.00 FS
77	1	*SUNDRIES	Necessary	500.00 FS	*47.20 FS
78	1	*REAR FENDER FUNCTION PLATE - LH	Dented	105.00 FS	*105.00 FS
79	1	*HINGE REINFORCEMENT FOR REAR LIF - LH	Dented	51.00 FS	*51.00 FS
80	1	*HIGH-LEVEL BRAKE LIGHT WITH SPRAY JET	Necessary	165.00 FS	*165.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 31,508.00 10,555.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	280.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	800.00	500.00
4	TO RESPRAY FRONT BUMPER	New	600.00	500.00
5	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	280.00
6	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	360.00	360.00
7	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID	New	480.00	480.00
8	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN	New	200.00	100.00
9	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	New	400.00	0.00
10	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	0.00
11	TO RESPRAY REAR BUMPER, REAR LID, HINGES, REAR END PANELLING, SPARE WHEEL HOUSING AND BOTH REAR FENDER	New	3,000.00	2,000.00
12	TO CARRY OUT DIAGNOSTIC CHECK	New	150.00	150.00
13	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. TO REPAIR SPARE WHEEL HOUSING AND BOTH REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,500.00	3,000.00
Gross Labour Cost (\$\$)			12,250.00	7,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >