



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 4083B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	MTG CRACKED	1,876.00	1,825.00
1	REAR BUMPER INNER PAD	SERVICEABLE	864.20	-
4	REAR BUMPER PARK SENSORS @\$396.70	SERVICEABLE	1,586.80	-
1	REAR BUMPER LOWER PAD	MTG CRACKED	1,015.90	685.00
1	REAR BUMPER LOWER CHROME GARNISH	DENTED	467.60	388.00
1	REAR BUMPER TOW COVER	SERVICEABLE	37.60	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	367.00	-
1	REAR BUMPER SPONGE	SERVICEABLE	366.40	-
2	REAR BUMPER REFLECTOR @\$235.00	O/S SCRATCHED	470.00	80.00
1	REAR BOOT LID	TO REPAIR SEE LABOUR	1,654.10	-
1	REAR BOOT CHROME MOULDING	SERVICEABLE	541.00	-
1	REAR BOOT EMBLEM LOGO	NECESSARY	89.40	89.40
1	REAR BOOT EMBLEM "E220D"	NECESSARY	94.10	94.10
1	REAR BOOT LID LOCK	TO REPAIR SEE LABOUR	454.00	-
1	REAR BOOT LOCK CATCH	TO REPAIR SEE LABOUR	67.00	-
1	REAR BOOT WEATHERSTRIP	SERVICEABLE	312.70	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	657.40	-
1	REAR END PANEL END PANEL	TO REPAIR SEE LABOUR	3,551.70	-
2	REAR TAIL LAMP ASSY @\$1390.60	O/S CUT	2,781.20	775.00
1	EXHAUST PIPE	TO REPAIR SEE LABOUR	1,865.40	-
2	EXHAUST TAIL PIPE CUTTER @\$373.00	SERVICEABLE	746.00	-
	LESS 10% DISCOUNT		-1,986.55	-393.65
			17,878.95	3,542.85
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR BOOT EMBLEM C&C (SN)	NECESSARY	60.00	60.00

Report Ref No. CS/AIS22004023/Kty3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET NUMBER PLATE & CASING (SN)	SERVICEABLE	60.00	-
			120.00	60.00
	<b>LABOUR</b>			
	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE,PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT, REAR BOOT LID,REAR BOOT LID LOCK,REAR BOOT LOCK CATCH,REAR END PANEL,REAR END PANEL END PANEL AND EXHAUST PIPE.		950.00	350.00
	TO CHECK WIRING SYSTEM.		40.00	20.00
	TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS.		750.00	480.00
	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS.	NOT NECESSARY	200.00	-
	TO APPLY RUST PROOF SEAL ON AFFECTED AREAS.	NOT NECESSARY	200.00	-
			2,140.00	850.00
<b>GRAND TOTAL</b>			<b>20,138.95</b>	<b>4,452.85</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,550.00</b>

Report Ref No. CS/AIS22004023/Kty3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.