

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004024/TVY3Q2**Date:** 25/04/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00127642103		
Claimant Vehicle No :	SJM4420H	Insured Vehicle No :	GBG7747Y		
Date of Loss:	25/04/2022	Nature of Claim:	TP	Claim No:	SNM22D202824/C02/KAHLEONG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM4420H		Engine No:	R18A1794496
Make & Model:	HONDA STREAM, 1.7 (A)		Chassis No:	RN61085196
Reg. Date:	02/01/2009 (Man. Year: 2008)		Odometer:	176344 km
Colour:	White			
Engine Capacity:	1799 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,144.00	3,316.00	1,828.00	35.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,790.00	1,730.00	2,060.00	54.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,934.00	5,046.00	3,888.00	43.52
Approved Total (Overridden) (\$\$)		4,050.00		
Nett Amount (\$\$)	8,934.00	4,050.00	4,884.00	54.67

INSPECTION

Date of Assignment:	28/04/2022		
Date Inspected:	11/05/2022	Inspected At:	JEW Motors (HQ) 60 Jalan Lam Huat Carros Centre #03-72 Singapore 737869
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2023)
Parts:	M1-MPV	HONDA STREAM 1.7 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM4420H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	778.00 FL	*678.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
3	1		*REAR BUMPER RH LOWER BRACKET	Not Necessary	14.00 FL	*- FL
4	1		*REAR BUMPER LH LOWER BRACKET	Bent	14.00 FL	*14.00 FL
5	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	18.00 FL	*- FL
6	1		*REAR BUMPER LH SIDE RETAINER	Cracked	18.00 FL	*18.00 FL
7	1		*REAR BUMPER TOWING COVER	Deformed	22.00 FL	*22.00 FL
8	1		*TAILGATE	Bent	938.00 FL	*938.00 FL
9	1		*TAILGATE WINDSREEN GLASS RUBBER MOULDING	Necessary	78.00 FL	*78.00 FL
10	1		*TAILGATE STREAM EMBLEM	Necessary	45.00 FL	*45.00 FL
11	1		*TAILGATE CENTRE EMBLEM	Necessary	23.00 FL	*23.00 FL
12	1		*TAILGATE OUTER GARNISH	Distorted	178.00 FL	*178.00 FL
13	1		*TAILGATE INNER HANDLE	Not Necessary	28.00 FL	*- FL
14	1		*TAILGATE INNER TRIM BOARD	Cracked	479.00 FL	*479.00 FL
15	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FL	*20.00 FL
16	1		*TAILGATE LOCK	Bent	110.00 FL	*110.00 FL
17	1		*TAILGATE LOCK CATCH	Not Necessary	45.00 FL	*- FL
18	1		*TAILGATE WEATHERSTRIP	Not Necessary	125.00 FL	*- FL
19	1		*RH TAILLAMP ASSY	Not Necessary	445.00 FL	*- FL
20	1		*LH TAILLAMP ASSY	Cut	445.00 FL	*445.00 FL
21	1		*END PANEL	Bent	404.00 FL	*404.00 FL
22	1		*END PANEL INNER GARNISH	Deformed	178.00 FL	*178.00 FL
23	1		*SET END PANEL INNER GARNISH CLIPS	Necessary	40.00 FL	*10.00 FL
24	1		*RH REAR FENDER INNER TRIM BOARD	Not Necessary	315.00 FL	*- FL
25	1		*SET RH REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FL	*- FL
26	1		*LH REAR FENDER INNER TRIM BOARD	Deformed	315.00 FL	*315.00 FL
27	1		*SET LH REAR FENDER INNER TRIM BOARD CLIPS	Necessary	50.00 FL	*10.00 FL
28	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	70.00 FS	*50.00 FS
29	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*40.00 FS
30	1		*TAILGATE REVERSE SENSOR	Not Necessary	680.00 FS	*- FS
31	1		*END PANEL SEAL	Necessary	70.00 FS	*30.00 FS
32	1		*REAR NUMBER PLATE	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,195.00	4,115.00
- List Item Discount on L Items 20.00/20.00% (S\$)	1,051.00	799.00
Total Parts (S\$)	5,144.00	3,316.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO PROVIDE WORKMANSHIP CUT/WELD AND REPLACING OF PARTS	New	1,600.00	700.00
2	SPRAY PAINT ON AFFECTED AND CONSISTENT AREAS	New	1,200.00	700.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	100.00	30.00
4	APPLY RUST CHEMICAL ON AFFECTED AREAS	New	120.00	30.00
5	REMOVE AND REPLACE BOOTLID REVERSE CAMERA	New	150.00	0.00
6	REMOVE AND REPLACE BOOTLID INNER MECHANISM	New	120.00	60.00
7	REMOVE AND REFIT REAR WINDSCREEN GLASS	New	220.00	120.00
8	REMOVE AND REPLACE REAR INNER GARNISH AND TRIM	New	180.00	60.00
9	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS	New	100.00	30.00
Gross Labour Cost (S\$)			3,790.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >