

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004033/RNY3M4**Date:** 12/05/2023**REFERENCE**

| | | | | | |
|-----------------------|---|----------------------|--------------------|-----------|-------------------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMCVSNW00021722201 | | |
| Claimant Vehicle No : | XE3541A | Insured Vehicle No : | GBJ1812R | | |
| Date of Loss: | 21/03/2022 | Nature of Claim: | TP | Claim No: | SNM22D201927/C02/TANCHC |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|---|-------------|-------------------|
| Reg No: | XE3541A | Engine No: | 12048988 |
| Make & Model: | VOLVO FLH290, 7.1 D 42R RSS CC WB4400 (M) | Chassis No: | YV2TH60A8HZ114410 |
| Reg. Date: | 10/10/2017 (Man. Year: 2017) | Odometer: | 210015 km |
| Colour: | Red | | |
| Engine Capacity: | 7146 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|--------------------|
| Front Tyre Size: | 295/80 R22.5 | Rear Tyre Size: | 295/80 R22.5 (D/D) |
| Front Left Side: | Triangle 8 mm | Rear Left Side: | Triangle 8/8 mm |
| Front Right Side: | Triangle 8 mm | Rear Right Side: | Triangle 8/8 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 2,940.00 | 1,116.00 | 1,824.00 | 62.04 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,480.00 | 2,390.00 | 2,090.00 | 46.65 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 7,420.00 | 3,506.00 | 3,914.00 | 52.75 |
| Approved Total (Overridden) (S\$) | | 2,800.00 | | |
| (S\$) | 7,420.00 | 2,800.00 | 4,620.00 | 62.26 |
| + GST 8.00/8.00% (S\$) | 593.60 | 224.00 | 369.60 | 62.26 |
| Nett Amount (S\$) | 8,013.60 | 3,024.00 | 4,989.60 | 62.26 |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|---|
| Date of Assignment: | 29/04/2022 | | |
| Date Inspected: | 11/10/2022 | Inspected At: | SC Auto Industries (S) Pte Ltd (HQ) 51 Senoko Road Singapore 758133 |
| Estimated Period of Repair: | 4.0 days | | |

Adjuster: MOHD RASUL**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

THE VEHICLE HAD COMMENCED ITS REPAIR AT THE TIME OF INSPECTION.

REPAIR DETAILS

| | | |
|---------------|--|--|
| Reference | | |
| Part Source: | (Last Synchronised: 12 May 2023) | |
| Parts: | N/A | VOLVO FLH290 7.1 D 42R RSS CC WB4400 (M) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for XE3541A) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------|-----------|--|-----------------|
| 1 | 1 | | *NUMBER PLATE | Bent | 25.00 F | *25.00 FL |
| 2 | 1 | | *ROUND STICKER | Necessary | 15.00 F | *15.00 FL |
| 3 | 1 | | *REAR RHS TAIL LAMP | Cracked | 300.00 F | *300.00 FL |
| 4 | 1 | | *REAR BUMPER | Repair | 750.00 F | *- FL |
| 5 | 1 | | *REAR SAFETY GUARD PANEL | Repair | 950.00 F | *- FL |
| 6 | 2 | | *SAFETY GUARD BRACKET | Bent | 900.00 F | *900.00 FL |
| | | | | | Sub Total (S\$) | 2,940.00 |
| | | | | | - List Item Discount on L Items 0.00/10.00% (S\$) | 0.00 |
| | | | | | Total Parts (S\$) | 1,116.00 |

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|-------------------------|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | LABOUR FOR REAR PORTION | New | 3,200.00 | 1,700.00 |
| 2 | LABOUR FOR PAINTING | New | 1,200.00 | 640.00 |
| 3 | LABOUR FOR WIRING | New | 80.00 | 50.00 |
| Gross Labour Cost (S\$) | | | 4,480.00 | 2,390.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >