

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004036/VQY3M4**Date:** 05/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00118312100

Claimant Vehicle No : SNA5016B **Insured Vehicle No :** SJU3898C

Date of Loss: 28/04/2022 Nature of Claim: TP Claim No: SNM22D202884/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNA5016B**

Make & Model: BMW 523I, 2.5 (A) Engine No: 07977601N52B25AF

Reg. Date: 29/11/2010 (Man. Year: 2010) Chassis No: WBAFP32050C546986

Colour: White Odometer: 148372 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 ZR19 Rear Tyre Size: 245/40 ZR19

Front Left Side: Head king 5 mm Rear Left Side: Head king 5 mm

Front Right Side: Head king 5 mm Rear Right Side: Head king 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,258.30	7,880.95	11,377.35	59.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,630.00	1,450.00	3,180.00	68.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,888.30	9,330.95	14,557.35	60.94
Approved Total (Overridden) (\$\$)		7,450.00		
Nett Amount (\$\$)	23,888.30	7,450.00	16,438.30	68.81

INSPECTION

Date of Assignment: 29/04/2022

Date Inspected: 29/04/2022 Inspected At: 8 KAKI BUKIT AVENUE 4
#01-49 PREMIER @ KAKI BUKIT SINGAPORE
415875
REPAIRER: J.E.W AUTO PTE LTD

Estimated Period of Repair: 5.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Sep 2022)
Parts:	143	BMW 523I 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA5016B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,665.00 FL	*1,665.00 FL
2	1		*BOOTLID LOGO	Necessary	72.00 FL	*72.00 FL
3	1		*BOOTLID RH LAMP ASSY	Cracked	432.00 FL	*432.00 FL
4	1		*BOOTLID LH LAMP ASSY	Cracked	432.00 FL	*432.00 FL
5	1		*BOOTLID WEATHERSTRIP	Deformed	232.00 FL	*232.00 FL
6	1		*BOOTLID LOCK	Serviceable	435.00 FL	*- FL
7	1		*BOOTLID LOCK CATCH	Serviceable	67.00 FL	*- FL
8	1		*BOOTLID RH HINGE	Serviceable	145.00 FL	*- FL
9	1		*BOOTLID LH HINGE	Serviceable	145.00 FL	*- FL
10	1		*BOOTLID INNER TRIM	Serviceable	283.00 FL	*- FL
11	1		*REAR BUMPER CENTRE RETAINER	Necessary	78.00 FL	*78.00 FL
12	1		*REAR BUMPER RH SIDE RETAINER	Necessary	132.00 FL	*132.00 FL
13	1		*REAR BUMPER LH SIDE RETAINER	Necessary	132.00 FL	*132.00 FL
14	1		*REAR BUMPER RH SIDE REVERSE SENSOR	Cut	237.00 FL	*150.00 FL
15	1		*REAR BUMPER RH CENTRE REVERSE SENSOR	Cut	237.00 FL	*150.00 FL
16	1		*REAR BUMPER LH CENTRE REVERSE SENSOR	Cut	237.00 FL	*150.00 FL
17	1		*REAR BUMPER LH SIDE REVERSE SENSOR	Cut	237.00 FL	*150.00 FL
18	4		*REAR BUMPER REVERSE SENSOR HOLDERS	Necessary	104.00 FL	*104.00 FL
19	4		*REAR BUMPER REVERSE SENSOR RUBBER SEAL	Necessary	88.00 FL	*88.00 FL
20	1		*REAR BUMPER REINFORCEMENT	Serviceable	613.00 FL	*- FL
21	1		*REAR BUMPER REINFORCEMENT INNER FRAME GARNISH	Serviceable	66.00 FL	*- FL
22	1		*REAR BUMPER INNER CENTRE FRAME GARNISH	Serviceable	67.00 FL	*- FL
23	1		*REAR BUMPER LOWER COVER	Cut	156.00 FL	*156.00 FL
24	1		*RH TAILLAMP ASSY	Cracked	545.00 FL	*545.00 FL
25	1		*RH TAILLAMP SIDE GARNISH	Serviceable	18.00 FL	*- FL
26	1		*LH TAILLAMP ASSY	Cracked	545.00 FL	*545.00 FL
27	1		*LH TAILLAMP SIDE GARNISH	Serviceable	18.00 FL	*- FL
28	1		*END PANEL	Dented	788.00 FL	*788.00 FL
29	1		*END PANEL INNER GARNISH	Serviceable	119.00 FL	*- FL
30	1		*SPARE TYRE PANEL TOP COVER BOARD	Serviceable	347.00 FL	*- FL
31	1		*REAR RH FENDER INNER TRIM COVER	Serviceable	421.00 FL	*- FL
32	1		*REAR LH FENDER INNER TRIM COVER	Serviceable	421.00 FL	*- FL
33	1		*BOOTLID SPOILER	Serviceable	1,850.00 FS	*- FS
34	1		*SET BOOTLID INNER TRIM CLIPS	Necessary	80.00 FS	*30.00 FS
35	1		*BOOTLID SEALANT	Necessary	80.00 FS	*30.00 FS
36	1		*END PANEL INNER GARNISH CLIPS	Necessary	60.00 FS	*30.00 FS
37	1		*END PANEL SEALANT	Necessary	75.00 FS	*30.00 FS
38	1		*REAR NUMBER PLATE	Serviceable	150.00 FS	*- FS
39	1		*REAR BUMPER	Cut	3,200.00 FS	*2,000.00 FS
40	1		*REAR BUMPER RH REFLECTOR	Serviceable	350.00 FS	*- FS
41	1		*REAR BUMPER LH REFLECTOR	Serviceable	350.00 FS	*- FS
42	1		*EXHAUST SILENCER (AKRAPOVIC)	Repair	3,800.00 FS	*- FS
43	1		*EXHAUST SILENCER GASKET (AKRAPOVIC)	Serviceable	85.00 FS	*- FS
44	1		*REAR LH FENDER INNER TRIM COVER CLIPS	Necessary	70.00 FS	*30.00 FS
45	1		*REAR RH FENDER INNER TRIM COVER CLIPS	Necessary	70.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	19,734.00	8,181.00
				- List Item Discount on L Items 5.00/5.00% (S\$)	475.70	300.05
				Total Parts (S\$)	19,258.30	7,880.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES ON AFFECTED AREAS	New	1,800.00	600.00
2	PUTTY AND RE-SPRAY ON AFFECTED AREAS	New	1,500.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM FOR PROPER FUNCTION	New	120.00	30.00
4	RE-SPRAY RUST CHEMICAL ON AFFECTED AREAS	New	180.00	30.00
5	REMOVE AND REPLACE BOOTLID MECHANISM TO NEW BOOTLID	New	220.00	60.00
6	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS	New	180.00	30.00
7	REMOVE AND REPLACE END PANEL INNER GARNISH, BOARDS AND TRIMS	New	350.00	0.00
8	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET	New	280.00	100.00
Gross Labour Cost (\$\$)			4,630.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >