

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004037/BQY3Q2**Date:** 23/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00049572200		
Claimant Vehicle No :	SJU8371Y	Insured Vehicle No :	GX7546L		
Date of Loss:	27/04/2022	Nature of Claim:	TP	Claim No:	SNM22D202870/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU8371Y	Engine No:	1NZY009861
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	MR053HY9305142162
Reg. Date:	30/12/2009 (Man. Year: 2009)	Odometer:	209009 km
Colour:	Yellow		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,423.22	2,558.82	8,864.40	77.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,420.00	1,660.00	3,760.00	69.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,843.22	4,218.82	12,624.40	74.95
Approved Total (Overridden) (S\$)		3,400.00		
(S\$)	16,843.22	3,400.00	13,443.22	79.81
+ GST 8.00/8.00% (S\$)	1,347.46	272.00	1,075.46	79.81
Nett Amount (S\$)	18,190.68	3,672.00	14,518.68	79.81

INSPECTION

Date of Assignment:	09/05/2022	
Date Inspected:	29/04/2022 Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	7.0 days	

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2023)
Parts: 143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJU8371Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	625.00 FL	*625.00 FL
2	1		*REAR BOOTLID E EMBLEM	Necessary	51.10 FL	*51.10 FL
3	1		*REAR BOOTLID VIOS EMBLEM	Necessary	51.10 FL	*51.10 FL
4	1		*REAR BOOTLID EMBLEM	Necessary	53.90 FL	*53.90 FL
5	1		*REAR BOOTLID HINGE RH	Not Damaged	182.25 FL	*- FL
6	1		*REAR BOOTLID HINGE LH	Not Damaged	182.25 FL	*- FL
7	1		*REAR BOOTLID LOCK	Not Damaged	381.90 FL	*- FL
8	1		*REAR BOOTLID LOCK STRIKER	Not Damaged	43.55 FL	*- FL
9	1		*REAR BOOTLID OUTER GARNISH	Not Damaged	281.70 FL	*- FL
10	1		*REAR BOOTLID WEATHERSTRIP	Not Damaged	185.10 FL	*- FL
11	1		*REAR BUMPER	Cut	474.80 FL	*474.80 FL
12	1		*REAR BUMPER SIDE RETAINER RH	Necessary	98.40 FL	*98.40 FL
13	1		*REAR BUMPER SIDE RETAINER LH	Necessary	98.40 FL	*98.40 FL
14	1		*REAR BUMPER BRACKET RH	No such part	131.35 FL	*- FL
15	1		*REAR BUMPER BRACKET LH	No such part	131.35 FL	*- FL
16	1		*REAR BUMPER REFLECTOR RH	Broken	87.60 FL	*87.60 FL
17	1		*REAR BUMPER REFLECTOR LH	Not Damaged	87.60 FL	*- FL
18	1		*REAR BUMPER SUPPORT BRACKET RH	No such part	33.20 FL	*- FL
19	1		*REAR BUMPER SUPPORT BRACKET LH	No such part	33.20 FL	*- FL
20	1		*REAR TAILLAMP ASSEMBLY RH	Broken	409.60 FL	*409.60 FL
21	1		*REAR TAILLAMP ASSEMBLY LH	Not Damaged	409.60 FL	*- FL
22	1		*REAR END PANEL	Not Damaged	682.10 FL	*- FL
23	1		*REAR END PANEL TOP GARNISH	Not Damaged	211.10 FL	*- FL
24	1		*REAR SPARE TYRE PANEL TOP BOARD	Not Damaged	172.10 FL	*- FL
25	1		*REAR SPARE TYRE PANEL SIDE SPONGE RH	Not Damaged	287.00 FL	*- FL
26	1		*REAR SPARE TYRE PANEL SIDE SPONGE LH	Not Damaged	377.25 FL	*- FL
27	1		*REAR SPARE TYRE PANEL CENTRE SPONGE	Not Damaged	378.20 FL	*- FL
28	1		*REAR SPARE TYRE PANEL	Not Damaged	673.20 FL	*- FL
29	1		*REAR FLOOR SIDE EXTENSION PANEL RH	Not Damaged	134.70 FL	*- FL
30	1		*REAR FLOOR SIDE EXTENSION PANEL LH	Not Damaged	134.70 FL	*- FL
31	1		*REAR FENDER RH	Dented	989.00 FL	*989.00 FL
32	1		*REAR TAILLAMP PANEL RH	Bent	231.20 FL	*231.20 FL
33	1		*REAR FENDER INNER TRIM RH	Not Damaged	224.10 FL	*- FL
34	1		*REAR FENDER INNER SHIELD RH	Broken	175.00 FL	*175.00 FL
35	1		*REAR FENDER AIR DUCT RH	Not Damaged	131.70 FL	*- FL
36	1		*REAR SHOCK ABSORBER RH	Not Damaged	290.00 FL	*- FL
37	1		*REAR WHEEL HUB WITH BEARING RH	Not Damaged	550.00 FL	*- FL
38	1		*REAR AXLE	Not Damaged	2,850.00 FL	*- FL
39	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
40	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
41	1		*SET REAR TAILLAMP CLIPS	Not Necessary	50.00 FS	*- FS
42	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	40.00 FS	*- FS
43	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
44	1		*SET REAR FENDER INNER SHIELD CLIPS	Necessary	20.00 FS	*20.00 FS
45	1		*REAR BOOTLID SEALANT	Not Necessary	150.00 FS	*- FS
46	1		*REAR END PANEL SEALANT	Not Necessary	150.00 FS	*- FS

Report was unsubmitted during this print-out.

5/23/23, 8:46 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	150.00 FS	*- FS
48	1		*REAR FENDER SEALANT	Not Necessary	150.00 FS	*- FS
49	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	120.00 FS	*- FS
50	1		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	250.00 FS	*- FS
51	1		*REAR WHEEL RIM RH	Not Necessary	800.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					14,554.30	3,395.10
- List Item Discount on L Items 25.00/25.00% (\$\$)					3,131.08	836.28
Total Parts (\$\$)					11,423.22	2,558.82
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE & REFIX PARTS	New	1,800.00	800.00
2	TO SPRAY PAINT AFFECTED AREAS	New	1,600.00	600.00
3	WIRING & BULB CHECK	New	100.00	0.00
4	TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	150.00	120.00
5	TO TRANSFER REAR BOOTLID MECHANISM	New	150.00	80.00
6	TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR	New	120.00	60.00
7	TO REMOVE & REFIX REAR EXHAUST PIPE TO FACILITATE REPAIRS	New	150.00	0.00
8	TO APPLY ANTI RUST ON AFFECTED PARTS	New	120.00	0.00
9	TO REMOVE & REFIX INTERIOR UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	0.00
10	TO REMOVE & REFIX REAR UNDERCARRIAGE	New	350.00	0.00
11	TO CONDUCT FOUR WHEEL ALIGNMENT	New	150.00	0.00
12	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
13	TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT ,PROGRAMMING & CALIBRATION	New	480.00	0.00
Gross Labour Cost (S\$)			5,420.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >