



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 7119J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER REFLECTOR GARNISH	BROKEN	168.00	150.00
1	REAR BUMPER	DENTED	1,050.00	970.00
2	REAR BUMPER RETAINER	NOT NECESSARY	154.00	-
1	REAR BUMPER THIRD BRAKE LAMP	BROKEN	336.00	336.00
1	TAILGATE ASSY	DENTED	4,060.00	3,770.00
1	TAILGATE LOCK	JAMMED	336.00	336.00
1	TAILGATE CHROME GARNISH	BROKEN	504.00	468.00
1	TAILGATE TRIMBOARD	NOT NECESSARY	770.00	-
1	TAILGATE LOGO	NECESSARY	364.00	338.00
1	REAR WIPER MOTOR	NOT NECESSARY	476.00	-
1	REAR NUMBER PLATE LAMP	NOT NECESSARY	105.00	-
1	TAILGATE LOCK SWITCH	NOT NECESSARY	203.00	-
2	TAILLAMP RH/LH	BROKEN (1PIECE ONLY)	1,260.00	630.00
1	END PANEL INNER	DENTED	784.00	728.00
1	END PANEL OUTER	DENTED	2,072.00	1,924.00
1	END PANEL TOP GARNISH	BROKEN	230.00	230.00
1	REAR FLOOR PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR CHASSIS PANEL (NPA)	NOT NECESSARY	-	-
1	REAR BUMPER REFLECTOR GARNISH (ADDITIONAL)	NOT NECESSARY	168.00	-
	LESS 10% DISCOUNT		-1,304.00	-988.00
			11,736.00	8,892.00
10	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
2	REVERSE SENSOR (SN)	SHORTED	672.00	500.00
	LESS 10% DISCOUNT		-72.20	-
			649.80	530.00
	<u>SPECIAL NETT ITEMS</u>			
1	70 KM/HR (SN)	NECESSARY	10.00	10.00
1	3 PAX (SN)	NECESSARY	10.00	10.00

Report Ref No. CS/FCI22004038/Evy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR ADVERTISEMENT STICKER (SN)	NECESSARY	900.00	500.00
1	SEALANT (SN)	NECESSARY	50.00	40.00
			970.00	560.00
	<u>LABOUR</u>			
	LABOUR TO FACILITATE REPAIR. INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL.		1,000.00	800.00
	TO RESPRAY AFFECTED AREAS.		1,000.00	800.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		120.00	120.00
	TO REMOVE AND TRANSFER TAILGATE COMPONENTS.		200.00	50.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		50.00	30.00
	RUST PROOFING.		100.00	30.00
			2,470.00	1,830.00
GRAND TOTAL			15,825.80	11,812.00
RECOMMENDED COST OF REPAIRS				11,812.00

Report Ref No. CS/FCI22004038/Evy3m4

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.