



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 3852M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BONNET (WCP)	BUCKLED	550.00	550.00
2	FRT BONNET HINGES @\$50.00 (WCP)	BENT	100.00	100.00
1	FRT BONNET LOCK (WCP)	TWISTED	45.00	45.00
1	FRT GRILLE ASSY (WCP)	DISTORTED	125.00	125.00
4	GRILLE CLIPS @\$2.00 (WCP)	NECESSARY	8.00	8.00
1	FRT BUMPER (WCP)	DISTORTED	430.00	430.00
2	FRT BUMPER RETAINER @\$12.00 (WCP)	BENT	24.00	24.00
10	FRT BUMPER CLIPS @\$2.00 (WCP)	NECESSARY	20.00	20.00
1	FRT BUMPER LOWER GRILLE (WCP)	DISTORTED	55.00	55.00
1	FRT BUMPER TOW COVER (WCP)	TORN	35.00	35.00
2	FRT BUMPER LOWER GRILLE COVER @\$8.00 (WCP)	N/S MISSING, O/S NOT NECESSARY	16.00	8.00
1	FRT BUMPER REINFORCEMENT (WCP)	DISTORTED	230.00	230.00
1	FRT BUMPER CENTRE TOP BEAM (WCP)	BENT	65.00	65.00
1	FRT BUMPER TOP RUBBER SEAL (WCP)	TORN	25.00	25.00
2	HEADLAMP @\$380.00 (WCP)	HOLDER CRACKED	760.00	760.00
1	HEADLAMP SUPPORT PANEL ASSY (WCP)	BENT	430.00	430.00
1	BRACE PANEL (WCP)	BENT	35.00	35.00
1	AIRCON CONDENSER (WCP)	BENT / PUNCTURE	495.00	495.00
1	RADIATOR (WCP)	BENT / PUNCTURE	460.00	460.00
1	RADIATOR MOTOR (WCP)	NOT NECESSARY	175.00	-
1	RADIATOR MOTOR COWLING (WCP)	NOT NECESSARY	160.00	-
1	RADIATOR FAN BLADE (WCP)	NOT NECESSARY	48.00	-
1	SUPPORT TOP GARNISH (WCP)	TORN	45.00	45.00
8	TOP GARNISH CLIPS @\$2.00 (WCP)	NECESSARY	16.00	16.00
1	FRT LH FENDER (WCP)	DENTED / BUCKLED	250.00	250.00
1	BONNET STAND CLIPS (WCP) (ADDITIONAL)	MISSING	5.00	5.00
	COST PLUS 15%		691.05	632.40
			5,298.05	4,848.40

Report Ref No. CS/LPC22004040/Uty3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	FRT NUMBER PLATE (SN)	BENT	35.00	35.00
1	BOL RADIATOR COOLANT (SN)	NECESSARY	25.00	25.00
			60.00	60.00
	<u>LABOUR</u>			
	WIRE CHECKING		30.00	20.00
	REMOVE & REFIX AIRCON AND GAS		100.00	100.00
	LABOUR CHARGE		700.00	600.00
	SPRAY PAINTING		700.00	680.00
			1,530.00	1,400.00
	GRAND TOTAL		6,888.05	6,308.40
	RECOMMENDED COST OF REPAIRS			6,308.40
	LESS EXCESS			-4,000.00
	NETT LIABILITY			2,308.40

Report Ref No. CS/LPC22004040/Uty3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.