

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 4086H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT	DENTED / BENT	752.00	752.00
1	REAR BOOT CENTRE LOGO	NECESSARY	41.00	41.00
1	REAR BOOT LOCK	TWISTED	198.00	198.00
1	REAR BOOT INNER RUBBER	TWISTED	143.00	143.00
1	REAR BOOT "ATTRAGE" PLATE	NECESSARY	20.00	20.00
1	REAR RH TAIL LAMP	CRACKED	266.00	266.00
1	REAR BUMPER	DISTORTED	659.00	659.00
2	REAR BUMPER RETAINER @\$13.00	BENT	26.00	26.00
10	REAR BUMPER CLIPS @\$3.00	NECESSARY	30.00	30.00
1	REAR END PANEL	BADLY DENTED	402.00	402.00
1	REAR END PANEL TOP GARNISH	TWISTED	62.00	62.00
6	TOP GARNISH CLIPS @\$3.00	NOT NECESSARY	18.00	-
1	REAR BOOT OUTER MOULDING (CRACKED)	NOT CONSISTENT WITH THE IMPACT	318.00	-
1	REAR ANTENNA SENSOR	CRACKED	75.00	75.00
	LESS 20% DISCOUNT		-602.00	-534.80
			2,408.00	2,139.20
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSOR (SN)	SHORTED	250.00	200.00
			250.00	200.00
	<u>LABOUR</u>			
	WIRE CHECKING.		30.00	20.00
	REMOVE & REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR.		120.00	60.00
	REMOVE & REFIX REVERSE SENSOR.		80.00	50.00
	CAVITY PROTECTION ON ALL AFFECTED AREAS.		150.00	60.00
	LABOUR CHARGE.		700.00	680.00
	SPRAY PAINTING.		700.00	700.00
			1,780.00	1,570.00
	GRAND TOTAL		4,438.00	3,909.20

Report Ref No. CS/SMR22004044/Uqy3n2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,100.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/SMR22004044/Uqy3n2

CHUA KANG SENG

**Licensed Appraiser**