

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6824J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	553.00	553.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	428.40	-
1	REAR BUMPER STAY LH	NOT NECESSARY	80.30	-
10	REAR BUMPER CLIP @ \$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER SIDE BRACKET LH	NOT NECESSARY	35.60	-
1	REAR BUMPER SPONGE	NOT NECESSARY	119.50	-
1	REAR BUMPER UNDER COVER	DEFORMED	228.00	228.00
1	REAR BUMPER REFLECTOR LH	CUT	32.00	32.00
1	EXHAUST MUFFLER LH	BENT	967.70	967.70
1	EXHAUST PIPE CENTRE	BENT	730.10	730.10
	LESS 20% DISCOUNT		-639.32	-506.56
			2,557.28	2,026.24
	NETT ITEMS			
1	REVERSE SENSORS (N)	NOT WORKING	135.70	135.70
	LESS 10% DISCOUNT		-13.57	-13.57
			122.13	122.13
	SPECIAL NETT ITEMS			
2	REAR FENDER ADV. STICKER RH / LH @ \$100.00	NECESSARY	200.00	200.00
1	REAR BUMPER ADV. STICKER (SN)	NECESSARY	50.00	50.00
			250.00	250.00
	<u>LABOUR</u>			
	PANEL BEATING.		300.00	280.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE / REFIX REVERSE SENSOR.		120.00	30.00
	REMOVE / REFIX EXHAUST PIPE.		120.00	60.00
	VEHICLE TOWING FEE (NPA)	NOT NECESSARY	-	-
			840.00	620.00
	GRAND TOTAL		3,769.41	3,018.37

Report Ref No. NS/INC22004045/Ttcs2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,950.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC22004045/Ttcs2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser