



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBT 1107R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	NOT NECESSARY	58.00	-
1	BALANCER LH	NOT NECESSARY	18.00	-
1	N/S SIDE COWLING	CUT	75.00	75.00
1	N/S PANEL 1	CUT	50.00	50.00
1	N/S LOWER COVER SIDE	CUT	55.00	55.00
1	N/S FOOTBOARD	CUT	68.00	68.00
1	N/S SIDE MIRROR	CUT	35.00	35.00
1	N/S BRAKE LEVER	CUT	28.00	28.00
1	EXHAUST COVER	DISTORTED	55.00	55.00
1	MAIN STAND	TO REPAIR SEE LABOUR	85.00	-
1	EXHAUST	TO REPAIR SEE LABOUR	850.00	-
	LESS 10% DISCOUNT		-137.70	-36.60
			1,239.30	329.40
	<u>LABOUR</u>			
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF MAIN STAND AND EXHAUST.		180.00	160.00
			180.00	160.00
GRAND TOTAL			1,419.30	489.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				400.00

Report Ref No. CS/AWA22004048/Uqy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.