



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Ref: CS/AWA22004048/Uqy3e2 Date: 24/05/2022  Code: AWA	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	XD 7954X	Veh. Inspected	FBT 1107R
Policy No.	BVFCB0006702116	Coverage (\$)	0.00
Claim No.	NSV2200058/HLF	Excess (\$)	0.00
Assign From	HEW LEE FONG	Assign Date	29/04/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	YAMAHA NMAX	c.c	155
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	MH3SG5680MK100235	Colour	BLACK
Odometer	16675 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	110-70-13	IRC	7 mm
L/H Front Tyre			mm
R/H Rear Tyre	130/70-13	IRC	7 mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND O/S REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	22/04/2022	Inspection Date	29/04/2022
Survey held at	TEO SPRAY PAINTING BLK 6 DEFU LANE 10 DEFU IND PARK C #01-558 SINGAPORE 539187		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	