



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 7699G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TAILLAMP RH	CRACKED	682.00	388.00
1	REAR TAILLAMP INNER SEALER	NOT NECESSARY	72.60	-
1	REAR TAILLAMP PANEL RH	DENTED	339.70	339.70
1	REAR FENDER RH	DISTORTED	1,795.20	1,795.20
1	REAR CORNER PANEL RH	NOT NECESSARY	247.50	-
	LESS 25% DISCOUNT		-784.25	-630.73
			2,352.75	1,892.17
	<u>SPECIAL NETT ITEMS</u>			
1	REAR MIRROR RH SEALANT (SN)	NECESSARY	80.00	50.00
1	REAR MIRROR RH INNER SEAL (SN)	NECESSARY	120.00	50.00
1	SET REAR TAILLAMP CLIPS (SN)	NECESSARY	80.00	10.00
			280.00	110.00
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE PARTS.		2,000.00	600.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED.		1,800.00	400.00
	TO REMOVE, REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS.		150.00	30.00
	TO REMOVE UPHOLSTERY.		120.00	80.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.		150.00	60.00
	TO REMOVE AND REPLACE REAR WINDOW RH.		150.00	80.00
			4,370.00	1,250.00
	GRAND TOTAL		7,002.75	3,252.17

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,600.00
---	--	--	-----------------

Report Ref No. CS/SMO22004052/Avy3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.