



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

LKK

Ru31217146

TRAXA.

Denise.

DATE: 10/05/2022 OUR REF: UAPL1526
REPAIR ESTIMATE YOUR HONDA VEZEL NO: SMG8583R

- 1 REAR TAILGATE ASSY *Distorted*
- 1 REAR TAILGATE INNER TRIM BOARD *could*
- 1 REAR TAILGATE INNER LOCK *Damd*
- 1 REAR TAILGATE LOGO *New*
- 1 REAR TAILGATE INNER PULL POCKET *New*
- 1 REAR TAILGATE WEATHERSTRIP *lt*
- 1 REAR TAILGATE OPENING SWITCH SET *New*
- 1 REAR TAILGATE (HYBRID) EMBLEM *3 new*
- 1 REAR TAILGATE (VEZEL) EMBLEM *LH could.*
- 2 REAR TAILGATE LAMPS (LED) *LH New*
- 1 REAR TAILGATE OUTER GARNISH *New*
- 2 REAR TAILLAMP ASSY (LED) *LH could*
- 1 REAR END PANEL *Dented*
- 1 REAR END PANEL INNER GARNISH *Dented*
- 1 REAR KEYLESS SENSOR *2nd*
- 1 REAR WINDSCREEN GLASS MOULDING *New*
- 1 REAR BUMPER ASSY *Distorted*
- 2 REAR BUMPER BRACKET *New*
- 6 REAR BUMPER CLIPS *New*
- 1 REAR BUMPER BEAM *New*
- 2 REAR BUMPER LOWER REFLECTOR *could*
- 2 REAR BUMPER SIDE RETAINERS *New*
- 2 REAR BUMPER SIDE GARNISH *LH torn*
- 1 REAR BUMPER LOWER UNDER COVER GARNISH *Dented*
- 2 REAR FENDER WHEEL ARCH GARNISHS *LH Dented*
- 1 REAR L/H FENDER INNER GARNISH *3 Dented*
- 1 REAR R/H FENDER INNER GARNISH *3 Dented*
- 1 REAR FLOOR PANEL *Burled*
- 1 REAR L/H FLOOR PANEL SIDE JOINT *Revis*
- 1 REAR FLOOR BOARD COVER *Dented*
- 1 REAR FLOOR CARGO TRAY BOARD *Dented*
- 1 REAR EXHAUST BOX ASSY *Revis*
- 2 REAR EXHAUST MOUNTINGS *New*
- 1 REAR EXHAUST CHROME *New*
- 1 REAR EXHAUST HEAT SHIELD *torn*

\$	1585.60 1100
\$	418.60 285
\$	269.50 ✓
\$	42.00 ✗
\$	48.50 ✗
\$	227.90 ✓
\$	197.40 ✗
\$	58.60 ✓
\$	61.30 ✓
\$	1025.20 415
\$	453.60 ✗
\$	1561.20 495
\$	785.00 ✓
\$	212.60 ✓
\$	189.50 85
\$	134.50 ✓
\$	968.30 745
\$	97.00 ✗
\$	30.00 ✓
\$	38.70 ✗
\$	317.80 282
\$	140.80 ✓
\$	482.60 195
\$	325.00 ✓
\$	644.60 165
\$	613.70 305
\$	613.70 ✓
\$	1,184.60 ✓
\$	254.60 ✗
\$	289.30 ✓
\$	255.60 ✓
\$	890.40 ✗
\$	57.00 ✗
\$	102.20 ✗
\$	146.30 95
\$	14,723.20
\$	2,944.64
\$	<u>11,778.56</u>

LESS 20%.....

8115.90

6492.72



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三
 AUTOBAY @ KAKI BUKIT
 No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883
 TELEPHONE: 6748 2795 FAX: 6747 2373
 Registration No.: 203165/00D

SPECIAL NETT:

1 REAR REVERSE SENSOR *Demd*
 1 REAR NUMBER PLATE *320*
 1 REAR WINDSCREEN RUBBER *re*
 1 REAR CCTV CAMERA SET *new*

310

\$ ~~280.00~~ *200*
 \$ 50.00 ✓
 \$ 60.00 ✓
 \$ 480.00 ✗

LABOUR CHARGES:-

TO DISM/REFIX REAR HYBRID CONTROL UNIT AND RESET
 TO DISM/RENEW REAR EXHAUST PIPE
 TO DISM/REWIRE DAMAGED PORTION
 TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS
 TO PUTTY AND RESPRAY DAMAGED PORTION
 TO DISM/RENEW REAR REVERSE SENSOR/CCTV CAMERA
 TO SPARY UNDERCOATING IN REPAIR
 TO DISM/REFIT REAR TAILGATE GLASS

2980

\$ ~~450.00~~ *300.*
 \$ ~~100.00~~ *80*
 \$ ~~200.00~~ *30*
 \$ ~~1,800.00~~ *1200.*
 \$ ~~1,300.00~~ *1000.*
 \$ ~~180.00~~ *100.*
 \$ ~~200.00~~ *100.*
 \$ ~~150.00~~ *120.*
 \$ 17,028.56

Total: 97,827.22

L/S: 7.8K.

09 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

78K