

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SG 5515L

Qty	Description of Parts	Condition	Recommended (\$)
	<u>REPLACEMENT OF PARTS</u>		
1	PANEL.REAR BUMPER.O/S	BENT	160.00
1	DOOR RETAINER;EXTERIOR DOOR	BENT	35.00
1	NUMBER PLATE RECESS PAN;EXT.RR	CRACKED	168.00
1	EXTERIOR RR O/S CORNER;F/GLASS	CRACKED	817.00
1	SIDE SHEETMETAL PANEL	BENT	212.00
1	BOTTOM BOOT DOOR ASSY;RR ENG DR	BENT	1,274.00
1	O/S LOWER COOLER DOOR ASSY	BENT	1,470.00
2	LED LICENSE PLATE LAMP	CRACKED	42.00
1	LED INDICATOR LIGHT 24V;30541714 1 LED	CRACKED	67.00
1	LED STOP/TAIL LIGHT 24V;30541713 1 LED	CRACKED	69.00
1	REAR REVERSE LAMP;B9TL EU5	CRACKED	81.00
1	PANEL.REAR BUMPER.N/S	CRACKED	160.00
1	REAR ENGINE COMPARTMENT DOOR	BENT	3,104.00
			7,659.00
	<u>LABOUR</u>		
	(2) WORKSHOP LABOUR.		184.00
	CONTRACTOR'S REPAIR CHARGES.		2,600.00
			2,784.00
	GRAND TOTAL		10,443.00
RECOMMENDED COST OF REPAIRS			10,443.00

Report Ref No. CS3/AWA21012941/Tqy3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.