

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG22004055/EQY3E2

Date: 12/08/2022

REFERENCE

Insured/Claimant:	Bhavna Pte Ltd	Policy No:	1001459124	Claim No:	273617
Date of Loss:	28/04/2022	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP3896G	Engine No:	4P10C14791
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M)	Chassis No:	FEB21EA20506
Reg. Date:	12/08/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	S\$54,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	60,205.86	31,297.31	28,908.55	48.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,020.00	7,010.00	6,010.00	46.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	73,225.86	38,307.31	34,918.55	47.69
Approved Total (Overridden) (S\$)		30,650.00		
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	72,525.86	29,950.00	42,575.86	58.70
+ GST 7.00/7.00% (S\$)	5,076.81	2,096.50	2,980.31	58.70
Nett Amount (S\$)	77,602.67	32,046.50	45,556.17	58.70

INSPECTION

Date of Assignment:	29/04/2022		
Date Inspected:	29/04/2022	Inspected At:	Goldbell Engineering Pte Ltd 10 Tuas Ave 18 Singapore 638894
Estimated Period of Repair:	15.0 days		

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Jul 2022)		
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEB21ER4SDEB (CBU) (M) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for YP3896G)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CABIN HEAD	Dented	28,000.00 F	*10,000.00 FL
2	1		*PANEL ASSY, INSTRUMENT	Broken	2,219.40 F	*2,219.40 FL
3	1		*GRILLE, FRONT	Broken	912.96 F	*912.96 FL
4	1		*PANEL, CAB FR CORNER - RH	Missing	669.10 F	*669.10 FL
5	1		*PANEL, CAB FR CORNER - LH	Not Necessary	669.10 F	*- FL
6	1		*SEAL, CAB FR CORNER PANEL, RH	Missing	48.72 F	*48.72 FL
7	1		*GARNISH, FR PANEL (F: MK676263)	Broken	507.01 F	*507.01 FL
8	1		*MARK, FUSO	Necessary	203.69 F	*203.69 FL
9	1		*BEZEL, COMBINATION METER	Broken	2,219.40 F	*2,219.40 FL
10	1		*PANEL, I/PNL CENTER UPPER	Not Necessary	157.08 F	*- FL
11	1		*FRAME, I/PNL DRIVER	Not Necessary	229.41 F	*- FL
12	1		*FRAME, I/PNL PASSENGER	Not Necessary	402.80 F	*- FL
13	1		*BEZEL, METER	Broken	195.80 F	*195.80 FL
14	1		*PIPE, A/C COMPRESSOR DISCHARGE	Not Necessary	105.28 F	*- FL
15	1		*PIPE, A/C COMPRESSOR SUCTION	Not Necessary	274.39 F	*- FL
16	1		*CONDENSER ASSY, A/C REFRIGERANT	Not Necessary	903.75 F	*- FL
17	1		*PLATE, A/C CONDENSER BAFFLE	Not Necessary	79.18 F	*- FL
18	1		*COVER, FR BUMPER - LH	Not Necessary	449.03 F	*- FL
19	1		*COVER, FR BUMPER - RH	Missing	449.03 F	*449.03 FL
20	1		*CROSSMEMBER, CHASSIS FRAME	Not Necessary	1,253.92 F	*- FL
21	1		*BUMPER, FR	Dented	1,013.70 F	*1,013.70 FL
22	1		*HEADLAMP ASSY, RH	Broken	628.91 F	*628.91 FL
23	1		*LAMP ASSY, TURN SIGNAL, FR RH	Broken	338.21 F	*338.21 FL
24	1		*GARNISH, HEADLAMP, RH	Broken	175.00 F	*175.00 FL
25	1		*COMPANY STICKER	Necessary	300.00 FS	*200.00 FS
26	1		*GLASS WINDSHIELD	Broken	1,113.62 F	*1,113.62 FL
27	1		*WEATHERSTRIP WINDSHIELD	Torn	659.82 F	*659.82 FL
28	1		*HEATER ASSEMBLY	Broken	2,661.65 F	*2,661.65 FL
29	1		*BRAKE BOOSTER	Bent	1,334.00 F	*1,334.00 FL
30	1		*CLUTCH PUMP ASSY	Bent	219.60 F	*219.60 FL
31	1		*BRAKE BOOSTER BRACKET	Bent	30.11 F	*30.11 FL
32	1		*RADIATOR SPARE TANK	Broken	128.10 F	*128.10 FL
33	1		*STEERING COUPLING	Bent	1,118.79 F	*700.00 FL
34	1		*STEERING COVER	Crushed	166.62 F	*166.62 FL
35	1		*STEERING WHEEL	Bent	778.63 F	*778.63 FL
36	1		*METER ASSY	Broken	1,969.65 F	*1,969.65 FL
37	1		*GEAR & LINK ASSY, P/S	Broken	3,189.00 F	*2,000.00 FL
38	1		*LEVER, CAB FR MOUNTING ANCHOR	Broken	331.10 F	*331.10 FL
39	2		*CUSHION CAB FR MOUNTING	Bent	588.94 F	*588.94 FL
40	2		*BUSHING, CAB FR MOUNTING (T:ML300312)	Necessary	49.20 F	*49.20 FL
41	1		*BRACKET, CAB FR MOUNTING CROSSMEMBER RH	Bent	1,089.66 F	*1,089.66 FL
42	1		*BRACKET, CAB FR MOUNTING CROSSMEMBER LH	Not Necessary	1,221.56 F	*- FL
43	1		*RH SIDE MIRROR	Broken	126.70 F	*126.70 FL
44	1		*FRONT RH MIRROR STAY	Bent	580.95 F	*580.95 FL
45	1		*FRONT LH ROUND MIRROR	Broken	73.63 F	*73.63 FL
46	1		*STEP FR SIDE RH	Broken	369.66 F	*369.66 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					60,205.86	34,752.57
- List Item Discount on L Items 0.00/10.00% (S\$)					0.00	3,455.26
Total Parts (S\$)					60,205.86	31,297.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	240.00	180.00
2	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	New	6,000.00	3,600.00
3	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK	New	180.00	180.00
4	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	New	3,500.00	2,450.00
5	TO REMOVE AND REFIX FRONT DASHBOARD	New	700.00	600.00
6	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	New	2,400.00	0.00
Gross Labour Cost (\$\$)			13,020.00	7,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >