

FINAL COST OF REPAIR
(To be completed for only one type of item)

To: 1 TPTBN CHARLIE Unit	From:	Ref	BB71(1TPTBN)/D/CGTC/011/22 93FMD / MOS	
Description of Item:	Ops/Utility/Veh		SAF 1222:	SAF 1222 - BB71(1TPTBN)/D/CGTC/011/22
Part/Reg No: MID33769	Original Value: -		Date:	28 April 2022
Quantity: 01	CE/Non CE: -		MO/MR:	8202751444/19805411
Description of Damages and Costs of Repairs:			Date:	28 April 2022
			Accident Job No:	8202751444/19805411
<u>S/N</u> 1) Both sides front fender wheel arch damaged 1.1) Both sides front fender undershield damaged 1.2) Renew mudguard clips(QTY-26) 2) LH sideguard scratched and out of alignment 2.1) LH front antenna mount scratched 3) Front plastic bumper LH retainer damaged 3.1) Front plastic bumper shifted out of alignment 4) Spray paint on all above accident repaired areas <u>Incident Repair</u> <u>Man-hours</u> 5.00 1.00 1.00 2.00				
<u>S/N</u>	<u>Materials Cost</u>	<u>Unit Price</u>	<u>Qty</u>	<u>COST</u>
1)	Front Fender Wheel Arc LH	\$109.27	1	\$109.27
2)	Front Fender Wheel Arc RH	\$129.50	1	\$129.50
3)	Front Fender Undershield LH	\$19.27	1	\$19.27
4)	Front Fender Undershield RH	\$18.76	1	\$18.76
5)	Clip, Mud Guard	\$0.65	26	\$16.90
6)	Retainer NO.2 Front Bumper	\$17.48	1	\$17.48
7)	P3 Green Paint	\$26.00	1	\$26.00
Base/LEO Area Office's Assessment of Damages				
Labour Charges @ \$79.61 per hour X 9.00 hrs		=	\$718.29	
Total Cost of Parts / Materials Used		=	\$337.18	
Sub-contractor		=	-	
Assessment Fee		=	\$638.47	
Towing Service		=	\$265.24	
Total			\$1,959.18	
Estimated Time for Repair:			9 Hr	

*Delete whichever is not applicable

FINAL COST OF REPAIR

HARI
HARAN S/O
ANBALAGA
N

Digitally signed
by HARI HARAN
S/O ANBALAGAN
Date: 2022.05.26
15:35:46 +08'00'