



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 597T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	COVER,REAR BUMPER	BUCKLED	485.60	485.60
1	REINFORCEMENT SUB-ASSY,REAR BUMPER	TO REPAIR SEE LABOUR	332.70	-
1	COVER,REAR BUMPER,LOWER	SERVICEABLE	22.00	-
1	GUARD,REAR BUMPER,CENTER	DENTED	374.50	374.50
1	RETAINER,REAR BUMPER SIDE,LH	SERVICEABLE	132.60	-
1	RETAINER,REAR BUMPER SIDE,RH	SERVICEABLE	132.60	-
1	PANEL SUB-ASSY,BACK DOOR	TO REPAIR SEE LABOUR	1,147.80	-
1	PLATE,LUGGAGE COMPARTMENT DOOR NAME NO.2	NOT NECESSARY	54.60	-
1	PLATE,BACK DOOR NAME,NO.1	NOT NECESSARY	54.60	-
1	ORNAMENT SUB-ASSY,BACK DOOR	NOT NECESSARY	47.90	-
1	GARNISH SUB-ASSY,BACK DOOR,OUTSIDE	TO REPAIR SEE LABOUR	913.60	-
1	BOARD ASSY,BACK DOOR TRIM	SERVICEABLE	259.20	-
1	WEATHERSTRIP,BACK DOOR	SERVICEABLE	372.30	-
1	COVER,DECK TRIM,REAR	SERVICEABLE	126.70	-
1	PANEL SUB-ASSY,BODY LOWER BACK	TO REPAIR SEE LABOUR	651.00	-
1	STAY ASSY,BACK DOOR,LH	SERVICEABLE	242.50	-
1	STAY ASSY,BACK DOOR,RH	SERVICEABLE	242.50	-
1	HINGE ASSY,BACK DOOR,LH	TO REPAIR SEE LABOUR	61.00	-
1	HINGE ASSY,BACK DOOR,RH	TO REPAIR SEE LABOUR	61.00	-
	LESS 25% DISCOUNT		-1,428.67	-215.02
			4,286.03	645.08
<u>SPECIAL NETT ITEMS</u>				
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	95.00	60.00
2	WINDSCREEN SEALANT (SN)	NOT NECESSARY	150.00	-
1	WINDSCREEN MOULDING (SN)	SERVICEABLE	200.00	-
1	WINDSCREEN INNER SPONGE SEAL (SN)	SERVICEABLE	130.00	-

Report Ref No. CS/AGI22004060/Kqy3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILGATE STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	REAR TAILGATE STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
1	REAR BUMPER PROTECTOR (SN)	SERVICEABLE	180.00	-
1	SET REAR BUMPER RETAINER CLIP (SN)	NOT NECESSARY	85.00	-
1	END PANEL TRIM CLIP (SN)	NOT NECESSARY	65.00	-
1	SET BUMPER CLIP FRT (SN)	NOT NECESSARY	95.00	-
1	REAR NUMBER PLATE WITH MOULDING (SN)	SERVICEABLE	200.00	-
			2,060.00	60.00
	LABOUR			
	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	300.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REINFORCEMENT SUB-ASSY,REAR BUMPER,PANEL SUB-ASSY,BACK DOOR,GARNISH SUB-ASSY,BACK DOOR,OUTSIDE,PANEL SUB-ASSY,BODY LOWER BACK,HINGE ASSY,BACK DOOR,LH AND HINGE ASSY,BACK DOOR,RH.		2,200.00	200.00
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT ELECTRICAL WIRING,BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	480.00	-
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	480.00	-
	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT,VACUUM AND CHARGE-IN-GAS.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	250.00	-

Report Ref No. CS/AGI22004060/Kqy3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING FEES.	NOT NECESSARY	150.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,200.00	320.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	50.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	220.00	-
	TO REPLACE, REFILL AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO LIFT-UP/OUT ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	-
	TO REMOVE AND REFIT RADIATOR SUPPORT CROSS-MEMBER AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR.	NOT NECESSARY	380.00	-
	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS.	NOT NECESSARY	380.00	-
			10,290.00	570.00
GRAND TOTAL			16,636.03	1,275.08
RECOMMENDED COST OF REPAIRS				1,275.08

Report Ref No. CS/AGI22004060/Kqy3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.