



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 6365C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER-FR BUMPER	TO REPAIR SEE LABOUR	481.10	-
1	LAMP ASSY-HEAD LH	CRACKED	2,110.30	2,110.30
1	DEP MIRROR ASSY-OUTSIDE R	BROKEN	1,391.70	1,391.70
1	EMBLEM-BLUE DRIVE LH	NECESSARY	26.60	26.60
	LESS 20% DISCOUNT		-	-705.72
			4,009.70	2,822.88
	<u>SPECIAL NETT ITEMS</u>			
1	PANEL-FENDER LH (SN)	TO REPAIR SEE LABOUR	588.80	-
			588.80	-
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF COVER-FR BUMPER AND PANEL-FENDER LH.		800.00	525.00
	SPRAYPAINT CHARGE.		700.00	600.00
	CHECK ALL LIGHTING.		50.00	30.00
			1,550.00	1,155.00
	GRAND TOTAL		6,148.50	3,977.88
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			3,977.88

Report Ref No. NS/INC22004068/Tqcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.