

Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581) Email: motor@wahhong.sg Contact: 6773 7377 / 8778 3338 ROC NO. & GST REG NO.: (199806235M)

Our Ref : Vehicle No. : Make & Model :		UC398 SKH8368P VOLVO S60 T4		Page No. 1		
TY		DESCRIPTION	CONDITION		IRER'S ATE(S\$)	SURVEYOR'S ADJUSTMENT
1 1 1 1	Rear Door Rh	H (Repair refer to labor) H (Repair refer to labor) RH(Repair refer to labor)	Part Items Total:	-10%	2342.00 0.00 0.00 0.00 2342.00 -234.20 2107.80	1599.80 -10% 1439.82
			SN Items Tota	1:	0.00	
			Total Parts	3:	2107.80	

Steve (LKK) 4/5/21, 11.00m

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

merc PIP Mrc 4 ys



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

	Ref : <i>UC398</i> cle No. : SKH8368P e & Model : VOLVO S60 T4		Page No. 2
s/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	410
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	900
3	To remove and repair/refix wiring system at accident damaged area and check for all electrical proper function	60.00	39
4	To perform anti-rust treatment on affected areas	60.00	1360
			P/P - \$2799.82
_	Labour Total	: 1920.00	
	TOTAL (PARTS & LABOUR)	4027.80	