

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004073/KPA3Q2**Date:** 26/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700085967-03
Claimant Vehicle No :	SMP1402D	Insured Vehicle No :	SLV106X
Date of Loss:	26/04/2022	Nature of Claim:	TP
		Claim No:	6021674865SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP1402D		
Make & Model:	HONDA VEZEL, 1.5 X CVT ABS D/AIRBAG 2WD 5DR (A)	Engine No:	L15B4030596
Reg. Date:	04/04/2016 (Man. Year: 2015)	Chassis No:	RU11110593
Colour:	Metallic Brown	Odometer:	84189 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,899.12	4,373.44	525.68	10.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	1,220.00	380.00	23.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,499.12	5,593.44	905.68	13.94
Approved Total (Overridden) (\$\$)		4,450.00		
(\$\$)	6,499.12	4,450.00	2,049.12	31.53
+ GST 7.00/7.00% (\$\$)	454.94	311.50	143.44	31.53
Nett Amount (\$\$)	6,954.06	4,761.50	2,192.56	31.53
+ Car Rental (6.0 x S\$90.00/day + 7.00% GST) (\$\$)		577.80		
Nett Liability (\$\$)		5,339.30		

INSPECTION

Date of Assignment:	29/04/2022	
Date Inspected:	05/05/2022	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	5.0 days	

10/26/22, 11:51 AM

Adjuster Report

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	801.70 FL	*801.70 FL
2	1		*FRONT BUMPER LOWER SIDE GARNISH	Buckled	381.00 FL	*381.00 FL
3	1		*FRONT BUMPER REINFORCEMENT BRACKET	Bent	321.00 FL	*321.00 FL
4	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	17.00 FL	*17.00 FL
5	6		*FRONT BUMPER CLIP	Necessary	22.80 FL	*22.80 FL
6	1		*FRONT GRILLE BASE	Cracked	301.60 FL	*301.60 FL
7	1		*HEADLAMP LH	Mtg Cracked	1,999.30 FL	*1,999.30 FL
8	2		*FRONT GRILLE TOP MOULDING	Necessary	150.00 FL	*150.00 FL
9	1		*FRONT GRILLE TOP GARNISH	Serviceable	65.00 FL	*- FL
10	1		*FRONT GRILLE LOGO	Necessary	24.10 FL	*24.10 FL
11	6		*FRONT GRILLE CLIP	Necessary	22.80 FL	*22.80 FL
12	1		*BONNET	Bent	854.60 FL	*854.60 FL
13	1		*BONNET INNER RUBBER	Serviceable	24.00 FL	*- FL
14	1		*FRT LH FENDER ARP GARNISH	Mtg Cracked	153.00 FL	*153.00 FL
15	1		*AIR CON CONDENSER	Serviceable	568.10 FL	*- FL
16	1		*FRONT GRILLE OUTER COVER	Cracked	301.20 FL	*301.20 FL
17	1		*BONNET LOCK BRACKET	Cracked	38.70 FL	*38.70 FL
18	2		*HEADLAMP LOWER BRACKET	Cracked	78.00 FL	*78.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	6,123.90	5,466.80
- List Item Discount on L Items 20.00/20.00% (\$)	1,224.78	1,093.36
Total Parts (\$)	4,899.12	4,373.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX FRT BUMPER ASSY ,GRILLE ,HEADLAMPS ,BONNET & ATTACHMENT KNOCK AND REPAIR FRT SUPPORT PANEL ,FRT LH FENDER AND RE-ALIGN TO SAME	New	700.00	500.00
2	TO PUTTY AND RESPRAY ON FRT BUMPER ,REINFORCEMENT BONNET ,FRT SUPPORT PANEL ,FRT LH FENDER	New	800.00	720.00
3	REMOVE AND REFIX AIRCON CHECK VACUUM & REFILL GAS	New	100.00	0.00
Gross Labour Cost (\$\$)			1,600.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >