



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCR 6886R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEAD LAMP R/H (N) (CONSISTENT)	CRACKED	2,985.00	2,985.00
1	BUMPER FRT (N) (CONSISTENT)	DEFORMED	1,850.00	1,850.00
1	BUMPER REINFORCEMENT FRT (N) (CONSISTENT)	NOT NECESSARY	355.00	-
1	GRILLE (N) (CONSISTENT)	CRACKED	1,120.00	1,120.00
	LESS 10% DISCOUNT		-631.00	-595.50
			5,679.00	5,359.50
	<u>SPECIAL NETT ITEMS</u>			
1	BUMPER SPOILER FRT (SN) (CONSISTENT)	CRACKED	1,300.00	650.00
			1,300.00	650.00
	<u>LABOUR</u>			
	REMOVE & RPELACE ACCIDENT DAMAGED PARTS.		450.00	300.00
	SPRAY PAINTING ACCIDENT AFFECTED PARTS.		400.00	250.00
	CHECK ALL LIGHTING AFTER REPAIR .		60.00	30.00
			910.00	580.00
	GRAND TOTAL		7,889.00	6,589.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,250.00

Report Ref No. CC4/ASM22004076/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.