



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: LOH CYNTHIA			Ref: CS/ASM22004082/Any3m4 Date: 13/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4111G	Veh. Inspected	PC 7592G	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S2M03ZWS	Excess (\$)	0.00	
Assign From	LOH CYNTHIA	Assign Date	04/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE COMMUTER	c.c	2754	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GDH2232000824	Colour	SILVER	
Odometer	201291 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195R15C	MICHELIN	6 mm	
L/H Front Tyre	195R15C	MICHELIN	6 mm	
R/H Rear Tyre	195R15C	MICHELIN	6 mm	
L/H Rear Tyre	195R15C	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/04/2022	Inspection Date	04/05/2022	
Survey held at	UNIMOTOR COMPANY 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	