

友尼摩哆公司 UNIMOTOR COMPANY

一號加基或吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D TRAXA. GDH 2232000884 LKK DATE: 15/05/2022 OUR REF: UAPL 1488 15 74 REPAIR ESTIMATE YOUR TOYOTA HIROOF NO:PC7592G 2.155.80 4 1 REAR TAILGATE ASSY DE W 573.20 2 REAR TAILGATE ABSORBER WE M 21.60 4 REAR TAILGATE WINDSCREEN DAM KIT 20 20 2 REAR TAILGATE WINDSCREEN SPACE 71.60 ~ 1 REAR TAILGATE EMBLEM HEN 58.70 1 REAR TAILGATE EMBLEM (HIACE) 44.10 1 REAR TAILGATE TOYOTA GL EMBLEM Rond 1 REAR TAILGATE LOCK 479.90 X 1 REAR TAILGATE LOCK CONTROL NEW 93.10 1 REAR TAILGATE LOCK STRIKER 1 REAR TAILGATE LOCK OUTER OPENER NEW 209.80 × 1 REAR TAILGATE KEY ANTENNA SENSOR Dond 289 30 1 REAR TAILGATE OUTER CHROME GARNISH COLLECT 288.90 2 77.80 X 2 REAR TAILGATE NUMBER PLATE LAMPS THE MAN 444.10 1 REAR TAILGATE INNER TRIM BOARD Cuiled 1 REAR TAILGATE WEATHERSTRIP W 735.60 2 REAR TAILLAMP LOWER COVER DELLA 2 REAR TAILLAMP ASSY could 88 60 X 2 REAR TAILLAMP LOWER BRACKET LLE M 1 REAR BUMPER ASSY 30.00 10 REAR BUMPER CLIP 2 REAR BUMPER SIDE RETAINER 4 REAR BUMPER BRACKET 98 40 1 REAR END PANEL (OUTER) Devel 1.156.40 X 1 REAR END PANEL (INNER) Pare 511.40 1 REAR LIH END JOINT PANEL PARTY 511 40 158 60 1 REAR RIH END JOINT PANEL DELLED 1 REAR END PANEL TOP GARNISH 1 REAR FLOOR PANEL Ne rev 1 REAR SPARE TYRE CARRIER BRACKET BUT 568 60) 98 60 7 1 REAR SPARE TYRE CARRIER BRACKET

1 REAR SPARE TYRE SCREW & NUT

1 REAR EXHAUST PIPE

2 REAR EXHAUST PIPE MOUNTING 994.20 X 84.60 X 3,554.25 LESS 25% 10,662.75 SPECIAL NETT:-60.00 V 1 REAR WINDSCREEN GLASS DAM RUBBER HU 15.00 W S 1 REAR TAILGATE 70KM/H STICKER NE 280.00 20 1 REAR SET REVERSE SENSER 50.00 X 1 REAR NUMBER PLATE ME NW

275



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

LABOUR CHANGE -

TO DISM/REWIRE DAMAGED PORTION

TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS

TO PUTTY AND RESPRAY DAMAGED PORTION

TO 3PARY UNDERCOATING IN REPAIR

TO DISM/REFIX REAR SEAT, ROOF LINING IN REPAIR

TO DIS/RENEW REAR EXHAUST PIPE

TO DISM/RENEW REAR REVERSE SENSOR

TO DISM/REFIX REAR TOP CAMERA UNIT

TO SUPPLY COMPANY STRICKER ON THE REAR TAILGATE

TO DISM/RENEW FRONT WINDSCREEN GLASS

\$ 12000 30

s 1.80000 Sw

1,00000 800

22000 80

100.00 50

100.00 7

35000 180

160.00 12v.

total: 7744.05 1/5: 62K. 06 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: