

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22004084/GQCE2**Date:** 07/10/2022**REFERENCE**

Insured/Claimant:	VENTAKACHELAM RAMAN	Policy No:	2100404089-07	
Date of Loss:	29/03/2022	Nature of Claim:	OD	Claim No: 8068830909SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKR6707E</b>	Engine No:	CZC233017
Make & Model:	AUDI A3, 1.4 TFSI AMBIENTE MY 15 (A)	Chassis No:	WAUZZZ8V7F1096484
Reg. Date:	27/02/2015 (Man. Year: 2015)	Odometer:	45318 km
Colour:	Red		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$50,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,634.00	875.20	8,758.80	90.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,282.00	2,292.00	2,990.00	56.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,916.00</b>	<b>3,167.20</b>	<b>11,748.80</b>	<b>78.77</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	14,316.00	2,567.20	11,748.80	82.07
<b>+ GST 7.00/7.00% (S\$)</b>	1,002.12	179.70	822.42	82.07
<b>Nett Amount (S\$)</b>	<b>15,318.12</b>	<b>2,746.90</b>	<b>12,571.22</b>	<b>82.07</b>

**INSPECTION**

Date of Assignment:	04/05/2022	
Date Inspected:	29/04/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,377.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	1		*FRONT BUMPER TRIM COVER - RH	Not Necessary	182.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	175.00 FS	*- FS
5	4		*FRONT BUMPER PULL STRAP - LOWER	Not Necessary	231.00 FS	*- FS
6	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	43.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	122.00 FS	*- FS
8	1		*FRONT FENDER - RH	Buckled	954.00 FS	*763.20 FS
9	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	75.00 FS	*- FS
10	1		*FRONT FENDER BRACKET - RH	Not Necessary	46.00 FS	*- FS
11	5		*FRONT FENDER POP RIVET	Necessary	19.00 FS	*15.20 FS
12	1		*FRONT FENDER BRACE - RH	Bent	107.00 FS	*85.60 FS
13	1		*FRONT WHEEL HOUSING LINER	Not Necessary	183.00 FS	*- FS
14	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	93.00 FS	*- FS
15	1		*HEADLIGHT - RH	Not Necessary	2,810.00 FS	*- FS
16	1		*ALUMINIUM RIM	Not Necessary	1,303.00 FS	*- FS
17	1		*RUBBER VALVE	Not Necessary	4.00 FS	*- FS
18	1		*LIFT CYLINDER - RH	Not Necessary	211.00 FS	*- FS
19	1		*LIFT CYLINDER HOSE	Not Necessary	204.00 FS	*- FS
20	1		*SUNDRIES	Necessary	300.00 FS	*11.20 FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (S\$)</b>	<b>9,634.00      875.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,100.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>5,282.00</b>	<b>2,292.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >