

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ECICS Limited  
10 Eunus Road 8, #09-04A Singapore Post Centre  
Singapore 408600

**Our File No:** CS/ICS22004085/KQCN2**Date:** 06/06/2022**REFERENCE**

Insured/Claimant: NG SHU XUAN Policy No: MPC21P00152400  
Date of Loss: 24/04/2022 Nature of Claim: OD Claim No: DMPC2200168H

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMV1851J**  
Make & Model: MAZDA 6, 2.0 (A) Engine No: PE21259652  
Reg. Date: 13/02/2019 (Man. Year: 2018) Chassis No: JM6GL1072K0312511  
Colour: Metallic Pearl White Odometer: 60398 km  
Engine Capacity: 1998 cc  
Market Value/New Car Price: S\$94,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/55R17 Rear Tyre Size: 225/55R17  
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm  
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,752.80	2,189.00	5,563.80	71.77
Miscellaneous Items	1,253.36	50.00	1,203.36	96.01
Labour	900.00	600.00	300.00	33.33
Paintwork Labour	900.00	600.00	300.00	33.33
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,806.16</b>	<b>3,439.00</b>	<b>7,367.16</b>	<b>68.18</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,750.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,806.16</b>	<b>2,750.00</b>	<b>8,056.16</b>	<b>74.55</b>

**INSPECTION**

Date of Assignment: 04/05/2022

Date Inspected: 04/05/2022 Inspected At:

BLK 4 YEW TEE IND 393-H  
WOODLANDS ROAD  
SINGAPORE 677969  
REPAIRER: ZHONG CHENG ENTERPRISE

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS**

<b>Reference</b>		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 06 Jun 2022)	
<b>Parts:</b> 143	MAZDA 6 2.0 (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b> (Unsubmitted, no print-code for SMV1851J)		
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.		

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>Bumper, front</b> (WCP)	Repair	950.00 F	*- F
2	1		<b>Fender LH, front</b> (WCP)	Repair	180.00 F	*- F
3	1		<b>Fender moulding LH, front</b> (WCP)	Serviceable	60.00 F	*- F
4	1		<b>Fender shield LH, front</b> (WCP)	Serviceable	55.00 F	*- F
5	1		<b>Headlamp LH</b> (WCP)	Serviceable	1,650.00 F	*- F
6	1		<b>*FRONT DOOR OUTER MOUNLDING LH</b> (WCP)	Dented	70.00 F	*70.00 F
7	1		<b>*side panel skirting LH</b> (WCP)	Bent	350.00 F	*350.00 F
8	1		<b>*Bumper bracket LH, front</b> (WCP)	Serviceable	10.00 F	*- F
9	1		<b>*Bumper retainer, front</b> (WCP)	Serviceable	15.00 F	*- F
10	1		<b>Absorber LH, front</b> (WCP)	Serviceable	190.00 F	*- F
11	1		<b>Knuckle arm LH, front</b> (WCP)	Serviceable	185.00 F	*- F
12	1		<b>Lower arm LH, front</b> (WCP)	Serviceable	175.00 F	*- F
13	1		<b>Lower arm shaft LH, front</b> (WCP)	Serviceable	150.00 F	*- F
14	1		<b>Wheel hub bearing LH, front</b> (WCP)	Not Necessary	230.00 F	*- F
15	1		<b>Door glass LH, front</b> (WCP)	Cracked	365.00 F	*365.00 F
16	1		<b>Door handle outer LH, front</b> (WCP)	Serviceable	150.00 F	*- F
17	1		<b>Door hinge lower LH, front</b> (WCP)	Distorted	65.00 F	*65.00 F
18	1		<b>Door hinge upper LH, front</b> (WCP)	Distorted	65.00 F	*65.00 F
19	1		<b>Door inner lock LH, front</b> (WCP)	Serviceable	125.00 F	*- F
20	1		<b>Door LH, front</b> (WCP)	Bent	1,300.00 F	*500.00 F
21	1		<b>Door regulator motor LH, front</b> (WCP)	Jammed	105.00 F	*105.00 F
22	1		<b>Door trim inner LH, front</b> (WCP)	Serviceable	85.00 F	*- F
23	1		<b>Door view side mirror bracket LH</b> (WCP)	Missing	40.00 F	*40.00 F
24	1		<b>Door view side mirror LH, front</b> (WCP)	Broken	400.00 F	*400.00 F
25	1		<b>Door weatherstrip LH, front</b> (WCP)	Serviceable	48.00 F	*- F
26	1		<b>Sticker LH, body</b> (WCP)	Necessary	30.00 F	*30.00 F

F=Franchise part.

<b>Sub Total (\$\$)</b>	<b>7,048.00</b>	<b>1,990.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	704.80	199.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					<b>Total Parts (S\$)</b>	<b>7,752.80</b>	<b>2,189.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	<b>front tyre LH</b> Serviceable	230.00	0.00
2	1	<b>GST</b>	493.36	0.00
3	1	<b>tyre rim front LH</b> Serviceable	450.00	0.00
4	1	<b>wheel alignment</b>	50.00	50.00
5	1	<b>wheel balancing</b> Not Necessary	30.00	0.00
<b>Sub Total (\$\$)</b>			<b>1,253.36</b>	<b>50.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Paintwork Labour</b>				
1	<b>front and front LH portion</b>	New	900.00	600.00
<b>Labour Items</b>				
2	<b>panel beating/dismantle and refix front/LH portions</b>	New	900.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,800.00</b>	<b>1,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >