

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Yi Guang@Hagel Tan Abdullah Date: 05 May 2022

Preliminary Advice

Vehicle No	: SMV1851J	Accident Date	: 24/04/2022
Make	: MAZDA 6	Policy No.	: MPC21P00152400
Assignment Date	: 04/05/2022	Excess	: S\$0.00
Date of Inspection	: 04/05/2022	Est. Duration of Repair	: 4
Inspection At	: ZHONG CHENG ENTERPRISE PTE LTD - WOODLANDS (HQ) BLK 6 WOODLANDS ROAD, 399J YEW TEE INDUSTRIAL ESTATE SINGAPORE 678008		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,806.16
Revised Amount	:S\$	4,319.00
Check Items (Estimated)	:S\$	2,592.16
Total	:S\$	6,911.16

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	94,000.00
COE / PARF Rebate	:S\$	40,863.00

Salvage Value	:S\$
Margin for Repair	:S\$ 53,137.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

- (X) Other comments :
According to our surveyor, he found the damages of front bumper and headlamp are not consistent due to the accident.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.