



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 3464U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	MTG CRACKED	538.10	538.10
1	O/S FRONT BUMPER SIDE RETAINER	DENTED	10.40	10.40
10	FRONT BUMPER CLIPS @\$3.80	NECESSARY	38.00	38.00
1	O/S FRONT FENDER	BENT	517.70	517.70
1	O/S FRONT INNER SHIELD	SERVICEABLE	107.80	-
10	O/S FRONT INNER SHIELD CLIPS @\$3.80	NOT NECESSARY	38.00	-
1	O/S FRONT INNER PANEL-OUTER	TO REPAIR SEE LABOUR	109.40	-
1	O/S HEADLAMP	MTG CRACKED	1,216.80	1,216.80
1	O/S HEADLAMP LOWER BRACKET	SERVICEABLE	39.60	-
1	O/S FRONT SPORT RIM (ORIGINAL) 16	DENTED	358.70	358.70
1	O/S FRONT LOWER ARM	SERVICEABLE	178.50	-
1	O/S FRONT KNUCKLE ARM	SERVICEABLE	146.20	-
1	O/S FRONT KNUCKLE ARM BEARING	NOT NECESSARY	157.40	-
1	O/S FRONT SHOCK ABSORBER	SERVICEABLE	338.20	-
1	O/S FRONT SHOCK ABSORBER MOUNTING	SERVICEABLE	32.60	-
1	O/S FRONT SHOCK ABSORBER BEARING	SERVICEABLE	42.20	-
1	O/S FRONT SHOCK ABSORBER STOPPER	SERVICEABLE	25.20	-
1	O/S FRONT STABILIZER BAR LINKAGE	SERVICEABLE	65.60	-
	LESS 20% DISCOUNT		-792.08	-535.94
			3,168.32	2,143.76
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	O/S FRONT TYRE 16" (SN)	SERVICEABLE	180.00	-
			180.00	-
	<b><u>LABOUR</u></b>			
	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF O/S FRONT INNER PANEL-OUTER.		650.00	400.00
	TO APPLY UNDERSEALING.		30.00	30.00
	TO DISMANTLE AND CHECK FRONT UNDER-CARRIAGES.TO REPLACE AFFECTED PORTIONS.	NOT NECESSARY	180.00	-

Report Ref No. CS/SMR22004089/Ktcn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.		80.00	60.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		600.00	400.00
			1,540.00	890.00
GRAND TOTAL			4,888.32	3,033.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CS/SMR22004089/Ktcn2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.