

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22004091/AQCE2**Date:** 15/12/2022**REFERENCE**

Insured/Claimant: WIELAND METALS SINGAPORE (PTE) LTD

Policy No: 7210123870

Date of Loss: 28/04/2022

Nature of Claim: OD

Claim No: 6596422589SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNC3726M**

Make & Model: AUDI A4, 2.0 TFSI S-TRONIC (A)

Engine No: DEM032752

Reg. Date: 15/10/2021 (Man. Year: 2021)

Chassis No: WAUZZZF46MA071650

Colour: Blue

Odometer: 4380 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$185,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17

Rear Tyre Size: 225/50 R17

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	78,435.50	46,484.00	31,951.50	40.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	46,375.64	32,290.00	14,085.64	30.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	124,811.14	78,774.00	46,037.14	36.89
- Excess (S\$)	100.00	100.00	0.00	0.00
(S\$)	124,711.14	78,674.00	46,037.14	36.92
+ GST 7.00/7.00% (S\$)	8,729.78	5,507.18	3,222.60	36.92
Nett Amount (S\$)	133,440.92	84,181.18	49,259.74	36.92

INSPECTION

Date of Assignment: 04/05/2022

Date Inspected: 29/04/2022

Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 40.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,493.00 FS	*1,994.40 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	173.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Necessary	125.00 FS	*100.00 FS
4	1		*REAR BUMPER SECURING STRIP - UPPER	Necessary	249.00 FS	*198.80 FS
5	1		*REAR BUMPER SPOILER	Deformed	276.00 FS	*220.80 FS
6	2		*REAR BUMPER BRACKET - LH / RH	O/S Damaged	456.00 FS	*182.00 FS
7	2		*REAR LIGHT REFLECTOR INNER - LH / RH	Not Necessary	96.00 FS	*- FS
8	1		*REAR LIGHT REFLECTOR OUTER - LH / RH	Not Necessary	96.00 FS	*- FS
9	1		*TAIL LIGHT OUTER - LH / RH	O/S Cracked	2,270.00 FS	*908.00 FS
10	1		*TAIL LIGHT OUTER TRIM - LH / RH	O/S Cut	68.00 FS	*26.48 FS
11	1		*TAIL LIGHT INNER - LH / RH	O/S Cut	2,270.00 FS	*908.00 FS
12	1		*TAIL LIGHT INNER TRIM - LH / RH	O/S Cut / N/S Not Necessary	68.00 FS	*26.48 FS
13	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,131.00 FS	*- FS
14	2		*REAR BUMPER SEAL	Not Necessary	32.00 FS	*- FS
15	1		*REAR BUMPER GUIDE SECTION LOWER - LH / RH	O/S Damaged	100.00 FS	*40.16 FS
16	1		*REAR BUMPER GUIDE SECTION UPPER - LH / RH	O/S Cracked	52.00 FS	*20.16 FS
17	2		*GUIDE SECTION PIN	Not Necessary	6.00 FS	*- FS
18	1		*REAR BUMPER HOLDING STRAP - LH / RH	O/S Bent	188.00 FS	*74.80 FS
19	4		*REAR PARKING AID SENSOR - INNER / OUTER (NPA)	Not Necessary	0.00 FS	*- FS
20	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
21	1		*SET REAR BUMPER WIRING	Not Necessary	449.00 FS	*- FS
22	1		*BOOT LID OPENING CONTROL UNIT	Not Necessary	454.00 FS	*- FS
23	1		*BOOT LID OPENING SENSOR LINE	Not Necessary	228.00 FS	*- FS
24	1		*CONTROL UNIT RETAINER	Not Necessary	9.00 FS	*- FS
25	1		*REAR PACKING ADHESIVE	Necessary	21.00 FS	*16.72 FS
26	1		*REAR LID FLAP GASKET	Necessary	229.00 FS	*182.80 FS
27	1		*AUDI EMBLEM	Necessary	144.00 FS	*114.80 FS
28	1		*A4 EMBLEM	Necessary	104.00 FS	*82.80 FS
29	1		*TAILGATE CHROME TRIM STRIP - CENTER	Necessary	272.00 FS	*217.60 FS
30	1		*REAR SIDE PANEL FRAME - LH	Distorted	3,199.00 FS	*2,559.20 FS
31	1		*REAR FENDER - RH	Distorted	4,357.00 FS	*3,485.60 FS
32	2		*GROMMET	Necessary	4.00 FS	*3.04 FS
33	2		*BLIND RIVET STUD	Necessary	20.00 FS	*15.68 FS
34	1		*REAR WINDSCREEN	Necessary	1,287.00 FS	*1,029.60 FS
35	2		*REAR QUARTER GLASS - LH / RH	Necessary	1,460.00 FS	*1,167.20 FS
36	3		*PRIMER	Necessary	66.00 FS	*52.08 FS
37	1		*FUEL INSERT	Not Necessary	100.00 FS	*- FS
38	1		*REAR WHEEL HOUSING OUTER PANEL - LH	Dented	687.00 FS	*549.60 FS
39	1		*C PILLAR REINFORCEMENT INNER - LH LOWER	Dented	220.00 FS	*175.60 FS
40	1		*B-PILLAR INNER - LH	Dented	607.00 FS	*485.60 FS
41	1		*B-PILLAR REINFORCEMENT INNER - LH	Distorted	446.00 FS	*356.40 FS
42	1		*SIDE PANEL FRAME CLOSING ELEMENT INNER - LH	Dented	604.00 FS	*483.20 FS
43	1		*SIDE MEMBER REINFORCEMENT LOWER INNER - LH	Dented	394.00 FS	*315.20 FS
44	1		*REAR WHEEL HOUSING LINER - LH	Deformed	260.00 FS	*208.00 FS
45	1		*PITOGAM STICKER	Necessary	27.00 FS	*21.28 FS
46	1		*REAR DOOR - LH	Distorted	3,431.00 FS	*2,744.80 FS
47	1		*REAR DOOR OUTER SEAL - LH	Necessary	229.00 FS	*182.80 FS
48	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
49	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
51	1		*REAR DOOR SEALING STRIP	Not Necessary	19.00 FS	*- FS
52	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	943.00 FS	*- FS
53	1		*REAR DOOR CATCH - LH	Damaged	120.00 FS	*96.00 FS
54	1		*REAR DOOR SEAL INNER - LH	Deformed	247.00 FS	*197.20 FS
55	1		*REAR DOOR HINGE - LEFT UPPER	Damaged	43.10 FS	*34.48 FS
56	1		*REAR DOOR HINGE HALVES - LEFT UPPER	Damaged	44.80 FS	*35.84 FS
57	1		*REAR DOOR HINGE HALVES - LEFT LOWER	Damaged	45.50 FS	*36.40 FS
58	1		*REAR DOOR HINGE - LEFT LOWER	Damaged	45.50 FS	*36.40 FS
59	1		*REAR DOOR HANDLE TRIM PLATE - LH	Not Necessary	98.00 FS	*- FS
60	1		*REAR DOOR HOUSING - LH	Not Necessary	9.00 FS	*- FS
61	1		*REAR DOOR HANDLE COVER - LH	Not Necessary	7.00 FS	*- FS
62	1		*REAR DOOR HANDLE SENSOR - LH	Not Necessary	255.00 FS	*- FS
63	1		*REAR DOOR HANDLE EXTERIOR - LH	Not Necessary	47.00 FS	*- FS
64	2		*LH DOOR HANDLE UNDERLAY - FRONT / REAR	Not Necessary	8.00 FS	*- FS
65	1		*REAR DOOR MOUNTING BAR - LH (NPA)	Not Necessary	0.00 FS	*- FS
66	1		*REAR DOOR LOCK - LH	Not Necessary	630.00 FS	*- FS
67	1		*REAR DOOR STRIKER	Not Necessary	77.00 FS	*- FS
68	1		*REAR DOOR INNER PANEL COVER - LH	Not Necessary	37.00 FS	*- FS
69	1		*REAR DOOR LOCK BOWDEN CABLE - LH	Not Necessary	43.00 FS	*- FS
70	1		*REAR DOOR GUIDE TRIM STRIP - LH	Dented	265.00 FS	*212.00 FS
71	1		*REAR DOOR GLASS APERTURE SEAL - LH INNER	Not Necessary	125.00 FS	*- FS
72	1		*REAR DOOR GLASS GUIDE RAIL - LH	Not Necessary	79.00 FS	*- FS
73	1		*BLACK GLOSSY C-PILLAR TRIM - LH OUTER	Not Necessary	159.00 FS	*- FS
74	1		*BLACK GLOSSY B-PILLAR TRIM - LH OUTER	Cut	167.00 FS	*133.60 FS
75	1		*REAR DOOR WINDOW SLOT SEAL TRIM STRIP - LH	Dented	410.00 FS	*327.60 FS
76	1		*REAR DOOR WINDOW REGULATOR - LH	Damaged	305.00 FS	*244.00 FS
77	1		*REA DOOR WINDOW REGULATOR WITH MOTOR - LH	Not Necessary	371.00 FS	*- FS
78	1		*REAR DOOR WINDOW CONTROL UNIT	Not Necessary	840.00 FS	*- FS
79	1		*REAR DOOR BOARD - LH INNER	Not Necessary	2,471.00 FS	*- FS
80	1		*REAR DOOR TRIM PANEL WIRE HARNESS	Not Necessary	328.00 FS	*- FS
81	1		*SET REAR DOOR WIRING - LH	Cracked	587.00 FS	*469.60 FS
82	1		*FRONT DOOR - LH	Distorted	3,431.00 FS	*2,744.80 FS
83	1		*FRONT DOOR OUTER SEAL - LH	Necessary	229.00 FS	*182.80 FS
84	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
85	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
86	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
87	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	1,153.00 FS	*- FS
88	1		*FRONT DOOR CATCH - LH (NPA)	Not Necessary	0.00 FS	*- FS
89	1		*FRONT DOOR SEAL INNER - LH	Not Necessary	229.00 FS	*- FS
90	1		*FRONT DOOR HANLDE TRIM PLATE - LH	Not Necessary	98.00 FS	*- FS
91	1		*FRONT DOOR HOUSING - LH	Not Necessary	9.00 FS	*- FS
92	1		*FRONT DOOR COVER - LH	Not Necessary	7.00 FS	*- FS
93	1		*FRONT DOOR MOUNTING BAR - LH (NPA)	Not Necessary	0.00 FS	*- FS
94	1		*FRONT DOOR WINDOW GUIDE - LH	Cut	501.00 FS	*400.80 FS
95	1		*FRONT DOOR WINDOW GUIDE TRIM STRIP - LH	Dented	287.00 FS	*229.60 FS
96	1		*GLOS Y BLACK B-PILLAR TRIM - LH OUTER	Cut	256.00 FS	*204.40 FS
97	1		*FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - LH	Not Necessary	344.00 FS	*- FS
98	1		*FRONT DOOR WINDOW REGULATOR - LH	Not Necessary	305.00 FS	*- FS
99	1		*FRONT DOOR WINDOW REGULATOR WITH MOTOR - LH	Damaged	345.00 FS	*244.00 FS
100	1		*FRONT DOOR CONTROL UNIT - LH	Not Necessary	672.00 FS	*- FS
101	1		*FRONT DOOR BOARD - LH INNER	Not Necessary	2,945.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
102	1		*FRONT DOOR SILL TRIM STRIP - LH	Necessary	687.00 FS	*549.60 FS
103	1		*SEAT AIRBAG UNIT - LH	Necessary	1,688.00 FS	*1,350.40 FS
104	2		*CURTAIN AIRBAG UNIT - LH / RH	Activated	4,138.00 FS	*3,310.40 FS
105	1		*AIRBAG CONTROL UNIT	Activated	2,364.00 FS	*1,891.20 FS
106	2		*REAR AIRBAG CRASH SENSOR	Activated	777.60 FS	*777.60 FS
107	1		*CENTRAL PROTECTION FUSE	Activated	590.00 FS	*472.00 FS
108	1		*ROOF LINER	Crumpled	2,339.00 FS	*1,871.20 FS
109	2		*A-PILLAR TRIM UPPER - LH / RH - INNER	Deformed	458.00 FS	*366.40 FS
110	2		*B-PILLAR TRIM UPPER - LH / RH - INNER	Not Necessary	520.00 FS	*- FS
111	2		*C-PILLAR TRIM - LH / RH - INNER	Not Necessary	508.00 FS	*- FS
112	2		*D-PILLAR TRIM - LH / RH - INNER	Not Necessary	508.00 FS	*- FS
113	1		*B-PILLAR TRIM LOWER - LH INNER	Deformed	171.00 FS	*136.80 FS
114	1		*WHEEL HOUSING TRIM LOWER - LH INNER	Not Necessary	166.00 FS	*- FS
115	2		*FRONT GRAB HANDLE - LH / RH	Damaged	268.00 FS	*268.00 FS
116	2		*REAR GRAB HANDLE - LH / RH	Damaged	268.00 FS	*268.00 FS
117	2		*FRONT SEAT BELT - LH / RH	Activated	2,454.00 FS	*1,963.20 FS
118	2		*FRONT SEAT BELT HEIGHT ADJUSTER - LH / RH	Damaged	383.00 FS	*306.40 FS
119	1		*FRONT PASSENGER SEAT BACKREST COVER - LH	Torn	3,409.00 FS	*2,727.20 FS
120	1		*UTR CAMERA (NPA)	Not Necessary	0.00 FS	*- FS
121	1		*SET UTR CAMERA WIRING (NPA)	Not Necessary	0.00 FS	*- FS
122	3		*FOAM TUBE	Not Necessary	21.00 FS	*- FS
123	1		*FLAT CONTACT HOUSING	Not Necessary	11.00 FS	*- FS
124	2		*FLAT CONTACT HOUSING	Not Necessary	35.00 FS	*- FS
125	1		*RETAINING HOSE (NPA)	Not Necessary	0.00 FS	*- FS
126	2		*ALUMINIUM RIM	Cut	2,584.00 FS	*2,067.20 FS
127	2		*RUBBER VALVE	Necessary	8.00 FS	*5.92 FS
128	1		*EXHAUST TAIL PIPE TRIM - LH / RH	O/S Bent	766.00 FS	*306.00 FS
129	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
130	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
131	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
132	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
133	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
134	1		*1/4 GLASS SEALANT	Necessary	200.00 FS	*200.00 FS
135	1		*SUNDRIES	Necessary	1,000.00 FS	*278.32 FS
136	1		*ROUND CONNECTOR HSG WITH CABLE (Supplementary)	Cracked	290.00 FS	*231.60 FS
137	1		*VENT TRIM (Supplementary)	Deformed	75.00 FS	*59.36 FS
138	1		*BASS LOUNDSPEAKER (Supplementary)	Cracked	158.00 FS	*126.00 FS
139	1		*REAR DOOR WINDOW GUIDE - LH (Supplementary)	Torn	501.00 FS	*400.80 FS
140	1		*BUNGS (Supplementary)	Necessary	49.00 FS	*38.80 FS
141	1		*FRONT DOOR LOCK - LH (Supplementary)	Damaged	691.00 FS	*552.40 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 78,435.50 46,484.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO RENEW REAR WINDSCREEN AND BOTH 1/4 GLASS TO FACILITATE RENEWAL OF BOTH REAR FENDERS	New	900.00	900.00
3	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN	New	200.00	150.00
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND BOTH 1/4 GLASS	New	400.00	400.00
5	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER	New	800.00	800.00
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGES AND RENEW WHERE NECESSARY	New	1,400.00	1,400.00
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
8	TO DISMANTLE AND REINSTALL CENTER CONSOLE. RENEW AIRBAG CONTROL UNIT AND BOTH FRONT SEATBELT, ROOF LINING, BOTH CURTAIN AIRBAGS AND LHS FRONT SEAT AIRBAG	New	3,200.00	3,200.00
9	TO REMOVE AND RENEW LHS FRONT SEAT BACKREST COVER	New	780.00	780.00
10	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,800.00	1,800.00
11	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	700.00	560.00
12	TO SET UP THE VEHICLE ON CAR O-LINER TO FACILITATE THE REPAIR	New	2,400.00	2,400.00
13	TO DISMANTLE AND RENEW REAR BUMPER, LHS REAR DOOR AND LHS FRONT DOOR. TO REPAIR RHS REAR DOOR, REAR LID AND REAR END PANELLING. TO CUT OUT AND WELD BOTH REAR FENDERS, LHS REAR END PANELLING. TO CUT AND WELD BOTH REAR FENDERS, LHS REAR WHEEL HOUSING OUTER, LHS REAR SIDE PANEL REINFORCEMENT, LHS SILL PANEL REINFORCEMENT, LHS B-PILLAR REINFORCEMENT, LHS SILL PANEL AND LHS B-PILLAR. }	New	18,000.00	9,500.00
14	RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED }	New	0.00	0.00
15	TO RENEW BOTH REAR RIMS. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	560.00	320.00
16	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
17	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
18	TO RESPRAY REAR BUMPER, REAR LID, BOTH REAR FENDERS, LHS REAR DOOR, LHS FRONT DOOR, DOOR HANDLES, HINGES, RHS REAR DOOR, BOTH SILL PANEL, BOTH ROOF CHANNEL, BOTH DOOR ENTRANCES, BOTH DRAIN PANEL, LHS B-PILLAR AND REAR END PANELLING	New	12,000.00	7,450.00
19	TO RE-APPLY PAINT COATING (Supplementary)	New	811.64	486.00
Gross Labour Cost (\$\$)			46,375.64	32,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >