



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 9750Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT LH SHOCK ABSORBER (WCP)	NOT NECESSARY	280.00	-
1	FRT LH LOWER ARM (WCP)	BENT	595.00	595.00
1	FRT LH LOWER ARM BALL JOINT (WCP)	BENT	105.00	105.00
1	FRT LH KNUCKLE ARM (WCP)	BENT	295.00	295.00
1	FRONT LH KNUCKLE BEARING (WCP)	DAMAGED	220.00	220.00
1	FRT LH SPORTS RIM (WCP)	CUT	800.00	800.00
	COST PLUS 10%		229.50	201.50
			2,524.50	2,216.50
	<u>LABOUR</u>			
	WIRE CHECKING.	NOT NECESSARY	30.00	-
	REMOVE & REFIX FRT UNDERCARRIAGE.		200.00	120.00
	WHEEL BALANCING.	NOT NECESSARY	30.00	-
	4 WHEEL ALIGNMENT.		80.00	80.00
	LABOUR CHARGE.		400.00	300.00
	SPRAY PAINTING.		650.00	600.00
			1,390.00	1,100.00
GRAND TOTAL			3,914.50	3,316.50
RECOMMENDED COST OF REPAIRS				3,316.50
LESS EXCESS				-500.00
NETT LIABILITY				2,816.50

Report Ref No. CS/UOI22004098/Uvy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.