

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22004100/VNY3E2

Date: 21/07/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00082902100		
Claimant Vehicle No :	GBH2842H	Insured Vehicle No :	GBL4127E		
Date of Loss:	28/04/2022	Nature of Claim:	TP	Claim No:	SNM22D202901/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH2842H	Engine No:	1KD2754439
Make & Model:	TOYOTA HIACE, 2.0 (M)	Chassis No:	KDH2015029962
Reg. Date:	02/04/2018 (Man. Year: 2017)	Odometer:	139308 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,624.12	3,816.50	3,807.62	49.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,320.00	1,440.00	2,880.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,944.12	5,256.50	6,687.62	55.99
Approved Total (Overridden) (\$\$)		4,200.00		
(\$\$)	11,944.12	4,200.00	7,744.12	64.84
+ GST 7.00/7.00% (\$\$)	836.09	294.00	542.09	64.84
Nett Amount (\$\$)	12,780.21	4,494.00	8,286.21	64.84

INSPECTION

Date of Assignment:	09/05/2022	
Date Inspected:	05/05/2022 Inspected At:	Carsmith Private Limited (HQ) 13 KAKI BUKIT ROAD 4 #01-20 BARTLEY BIZ CENTRE Singapore 417807
Estimated Period of Repair:	5.0 days	

Adjuster: Thevan Thomas Karthikesavan

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 21 Jul 2022)	
Parts:	N/A	TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH2842H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	675.00 FL	*582.00 FL
2	1		*REAR BUMPER RETAINER LH	Necessary	46.00 FL	*46.00 FL
3	1		*REAR BUMPER RETAINER RH	Necessary	46.00 FL	*46.00 FL
4	1		*REAR BUMPER SPONGE	Not Necessary	118.00 FL	*- FL
5	1		*REAR BUMPER REFLECTOR LH	Not Necessary	75.00 FL	*- FL
6	1		*REAR BUMPER REFLECTOR RH	Not Necessary	75.00 FL	*- FL
7	1		*TAILGATE	Dented	2,235.50 FL	*1,755.00 FL
8	2		*TAILGATE HINGE RH LH	Serviceable	110.00 FL	*- FL
9	1		*TAILGATE EMBLEM - HIACE	Necessary	120.00 FL	*120.00 FL
10	1		*TAILGATE EMBLEM LOGO	Necessary	79.00 FL	*79.00 FL
11	1		*TAILGATE OUTER GARNISH	Scratched	365.00 FL	*286.00 FL
12	1		*TAILGATE LOCK	Jammed	145.00 FL	*145.00 FL
13	1		*TAILGATE LOCK CATCH	Serviceable	65.00 FL	*- FL
14	1		*TAILGATE STRIKER	Serviceable	60.00 FL	*- FL
15	2		*TAILGATE STOPPER RH / LH	Serviceable	120.00 FL	*- FL
16	2		*TAILGATE DAMPER RH / LH	Serviceable	710.00 FL	*- FL
17	1		*TAILGATE WEDGE STRIKER	Serviceable	65.00 FL	*- FL
18	1		*TAILGATE WEATHERSTRIP	Deformed	84.00 FL	*84.00 FL
19	2		*TAILLAMP LH / RH	Scratched	790.00 FL	*790.00 FL
20	1		*TAILGATE INNER TRIM	Serviceable	223.00 FL	*- FL
21	1		*REAR WINDSCREEN	Cracked	689.00 FL	*689.00 FL
22	1		*END PANEL - INNER	Repair	698.00 FL	*- FL
23	1		*END PANEL - OUTER	Repair	418.00 FL	*- FL
24	1		*REAR EXHAUST ASSY	Serviceable	486.00 FL	*- FL
25	1		*REAR SPARE TYRE BRACKET	Serviceable	308.00 FL	*- FL
26	1		*REAR NUMBER PLATE	Serviceable	100.00 FS	*- FS
27	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*20.00 FS
28	1		*8PAX STICKER	Necessary	70.00 FS	*30.00 FS
29	1		*70 KM STICKER	Necessary	70.00 FS	*30.00 FS
30	1		*SET REAR TAILGATE INNER TRIM CLIP	Necessary	40.00 FS	*20.00 FS
31	1		*SET REAR REVERSE SENSOR	Cut	400.00 FS	*200.00 FS
32	1		*JOINT SEALANT	Not Necessary	150.00 FS	*- FS
33	1		*WINDSCREEN SEALANT	Necessary	150.00 FS	*50.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					9,825.50	4,972.00
- List Item Discount on L Items 25.00/25.00% (\$\$)					2,201.38	1,155.50
Total Parts (\$\$)					7,624.12	3,816.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	New	100.00	30.00
2	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	New	200.00	30.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	30.00
4	REMOVE AND RENEW REAR EXHAUST	New	150.00	0.00
5	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
6	TRANSFER PARTS, ATTACHMENT FROM OLD LH	New	200.00	0.00
7	TRANSFER PARTS, ATTACHMENT FROM OLD RH	New	200.00	0.00
8	PANEL BEATING ON AFFECTED AREAS AND RENEW	New	1,500.00	600.00
9	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	600.00
10	APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	30.00
Gross Labour Cost (\$\$)			4,320.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >