

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EG122004102/ANY3E2

Date: 11/08/2022

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBF3433J

Insured Vehicle No : XE3360E

Date of Loss: 30/04/2022

Nature of Claim:

TP

Claim No: CDMCG22000808

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF3433J**

Make & Model: TOYOTA HIACE, 3.0 D TURBO 5DR (M)

Engine No: 1KD2650632

Reg. Date: 21/09/2016 (Man. Year: 2016)

Chassis No: JTFHT02PX00205997

Colour: Silver

Odometer: 259140 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size:

195 R15C

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,281.42	3,272.10	1,009.32	23.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	1,410.00	1,340.00	48.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,031.42	4,682.10	2,349.32	33.41
Approved Total (Overridden) (S\$)		3,700.00		
(S\$)	7,031.42	3,700.00	3,331.42	47.38
+ GST 7.00/7.00% (S\$)	492.20	259.00	233.20	47.38
Nett Amount (S\$)	7,523.62	3,959.00	3,564.62	47.38

INSPECTION

Date of Assignment: 04/05/2022

Date Inspected: 05/05/2022 Inspected At:

Ryder Auto Pte Ltd (HQ)

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
Singapore 417921

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Aug 2022)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF3433J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR O/S BUMPER TOP GARNISH	Repair	80.60 FL	*- FL
2	1		*REAR TAIL-GATE	Distorted	1,825.90 FL	*1,755.00 FL
3	1		*REAR TAIL-GATE WEATHERSTRIP	Not Necessary	320.00 FL	*- FL
4	1		*REAR TAIL-GATE TOYOTA EMBLEM	Necessary	82.00 FL	*55.00 FL
5	1		*REAR TAIL-GATE 70 KMPH EMBLEM	Necessary	15.00 FS	*15.00 FS
6	1		*REAR TAIL-GATE 10 PAX EMBLEM	Necessary	15.00 FS	*15.00 FS
7	1		*REAR TAIL-GATE TOYOTA HIACE EMBLEM	Necessary	60.00 FL	*60.00 FL
8	1		*REAR O/S TAIL LAMP	Cracked	420.20 FL	*345.00 FL
9	1		*REAR O/ S TAIL LAMP PANEL	Repair	325.00 FL	*- FL
10	1		*REAR N/S BODY PANEL SLIDING GUIDE	Not Necessary	420.40 FL	*- FL
11	1		*REAR N/S BODY PANEL	Dented	1,867.80 FL	*1,867.80 FL
12	1		*REAR WINDSCREEN MOULDING	Necessary	120.00 FS	*120.00 FS
13	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
					Sub Total (\$\$)	
					5,631.90	4,292.80
					- List Item Discount on L Items 25.00/25.00% (\$\$)	
					1,350.48	1,020.70
					Total Parts (\$\$)	
					4,281.42	3,272.10

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PARTS, STRAIGHTEN & WELDING	New	1,400.00	600.00
2	TO SPRAY PAINTING	New	800.00	500.00
3	TO REMOVE & REFIT REAR WINDSCREEN	New	140.00	120.00
4	TO REMOVE AND REFIT REAR REVERSE CAMERA	New	50.00	50.00
5	TO CHECK WIRING	New	80.00	30.00
6	TO RE-SEAL ANTI-RUST	New	50.00	50.00
7	TO CHECK AND RESET ELECTRICAL SYSTEM	New	80.00	0.00
8	TO REMOVE AND REFIT REAR UPHOLSTERY TO FACILITATE REPAIR	New	150.00	60.00
Gross Labour Cost (\$\$)			2,750.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >