

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22004103/UQY3E2

Date: 07/06/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00059232100
Claimant Vehicle No : SJR6665D **Insured Vehicle No :** YP2718U
Date of Loss: 19/04/2022 Nature of Claim: TP Claim No: SNM22D202961/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR6665D**
Make & Model: HONDA CITY, 1.5 L I-VTEC (A) Engine No: L15A71809032
Reg. Date: 06/07/2009 (Man. Year: 2009) Chassis No: MRHGM26509P020342
Colour: White Odometer: 254334 km
Engine Capacity: 1497 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45Z R16 Rear Tyre Size: 205/45Z R16
Front Left Side: Windforce 6 mm Rear Left Side: Windforce 6 mm
Front Right Side: Windforce 6 mm Rear Right Side: Windforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,007.58	855.18	152.40	15.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	1,290.00	2,090.00	61.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,387.58	2,145.18	2,242.40	51.11
+ GST 7.00/7.00% (S\$)	307.13	150.16	156.97	51.11
Nett Amount (S\$)	4,694.71	2,295.34	2,399.37	51.11

INSPECTION

Date of Assignment: 04/05/2022
Date Inspected: 06/05/2022 Inspected At: Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610
Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2022)
Parts:	143	HONDA CITY 1.5 L I-VTEC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR6665D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLIGHT ASSY,L	Deep Cut	243.07 FS	*243.07 FS
2	1		*FACEFR.BUMPER	Distorted	344.85 FS	*344.85 FS
3	1		*BEAM L FR BUMPER	Cracked	20.62 FS	*20.62 FS
4	1		*BEAM COMP FR BUMPER	Not Necessary	122.40 FS	*- FS
5	1		*BASE FR GRILLE	Cracked	76.35 FS	*76.35 FS
6	1		*MOULDINGFR.GRILLE	Cracked	107.10 FS	*107.10 FS
7	1		*EMBLEM H	Necessary	13.72 FS	*13.72 FS
8	1		*NUT,PUSH 3MM (2PCS)	Necessary	3.15 FS	*3.15 FS
9	1		*CLIP, BUMPER FACE (5PCS)	Necessary	14.62 FS	*14.62 FS
10	1		*CLIP, ABUMPER (4PCS)	Necessary	11.70 FS	*11.70 FS
11	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					1,007.58	855.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT FR LIGHTING MECANISMS & FOCUS	New	180.00	120.00
2	STRAIGHTEN ALIGN FR L FENDER	New	1,500.00	650.00
3	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	New	1,700.00	520.00
Gross Labour Cost (S\$)			3,380.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >